

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008459/KEA3Q2
Date: 10/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100444019
Claimant Vehicle No :	SGZ8391Z	Insured Vehicle No :	SKX7444A
Date of Loss:	11/08/2021	Nature of Claim:	TP
		Claim No:	9067664130SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ8391Z		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX634481
Reg. Date:	20/11/2007 (Man. Year: 2007)	Chassis No:	MR053HY9305031490
Colour:	Metallic Black	Odometer:	257399 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	CST 6 mm	Rear Left Side:	RAPID 9 mm
Front Right Side:	CST 6 mm	Rear Right Side:	RAPID 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,190.32	2,795.51	2,394.81	46.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,720.00	1,480.00	46.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,390.32	4,515.51	3,874.81	46.18
Approved Total (Overridden) (S\$)		3,600.00		

Nett Amount (S\$)	8,390.32	3,600.00	4,790.32	57.09
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Medical Costs (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,527.45		

INSPECTION

Date of Assignment: 12/08/2021

Date Inspected: 12/08/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Ngs Automotive (HQ)
BLK 10 AMK IND PK 2A #02-01
Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	684.05 FL	*589.10 FL
2	2		*REAR BOOT HINGE RH/LH	Repair	99.40 FL	*- FL
3	2		*BAR ,REAR BOOT RH/LH	Repair	93.42 FL	*- FL
4	1		*REAR BOOT INNER LOCK	Distorted	126.28 FL	*126.28 FL
5	1		*REAR BUMPER	Bent	496.04 FL	*451.60 FL
6	2		*REAR BUMPER RETAINER UPPER RH/LH	Distorted	85.00 FL	*85.00 FL
7	2		*REAR BUMPER RETAINER LOWER RH/LH	Distorted	211.00 FL	*211.00 FL
8	2		*REAR BUMPER SEAL RH/LH	No such part	106.00 FL	*- FL
9	1		*REAR END PANEL	Bent	592.22 FL	*575.00 FL
10	1		*REAR END PANEL GARNISH	Distorted	226.83 FL	*226.83 FL
11	1		*LUGGAGE COMPARTMENT PANEL	Repair	639.50 FL	*- FL
12	1		*CARRIER ASSY ,SPARE WHEEL	Serviceable	65.34 FL	*- FL
13	1		*LUGGAGE COMPARTMENT BOARD	Serviceable	175.91 FL	*- FL
14	1		*COVER,ROOM PARTITION	Serviceable	203.00 FL	*- FL
15	1		*BOARD ,ROOM PARTITION LH	Serviceable	154.50 FL	*- FL
16	1		*WEATHERSTRIP ,TRUNK	Distorted / Dented	137.42 FL	*137.42 FL
17	1		*STRIKER ,LUGGAGE COMPARTMENT	Repair	23.00 FL	*- FL
18	2		*TAILLAMP RH/LH	Cracked	486.40 FL	*486.40 FL
19	2		*TAILLAMP GASKET RH/LH	Necessary	78.92 FL	*78.92 FL
20	1		*TAILLAMP LOWER PANEL EXTENSION LH	Bent	135.00 FL	*135.00 FL
21	1		*REAR FENDER LH	Repair	1,011.00 FL	*- FL
22	1		*SPARE TYRE BOLT	Serviceable	162.73 FL	*- FL
23	1		*REAR BOOT BADGE	Necessary	47.53 FL	*47.53 FL
24	1		*EMBLEM G	Necessary	44.52 FL	*44.52 FL
25	1		*EMBLEM VIOS	Necessary	54.80 FL	*54.80 FL
26	2		*REAR BUMPER LOWER REFLECTOR RH/LH	Scratched	188.62 FL	*188.62 FL
27	16		*CLIPS,LUGGAGE COMPARTMENT TRIM	Not Necessary	80.00 FS	*- FS
28	4		*CLIPS,TAILLAMP ,TOP/BOT LH/RH	Necessary (2 PCS ONLY)	34.00 FS	*17.00 FS
29	1		*REAR NO PLATE C/W CASING	Serviceable	50.00 FS	*- FS
30	1		*PARKING SENSOR	Dented	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,772.43	3,655.02
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,582.11	859.51
Total Parts (\$\$)	5,190.32	2,795.51

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REAR DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART REFIT INTO POSITION	New	1,600.00	850.00
2	TO SPRAY REAR PORTIONS	New	1,400.00	800.00
3	TO TRANSFER RR BOOT MECHANISM	New	150.00	50.00
4	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
Gross Labour Cost (\$)			3,200.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >