

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO21008460/Atf3n2	
50 RAFFLES PLACE #03-03			Date: 18/10/2021	
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 7705M		Veh. Inspected	GBB 8193P
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2102386/GPL		Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG		Assign Date	12/08/2021
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200		c.c	1461
Engine No.	HIDDEN		Year of Reg.	2010
Chassis No.	JN1YBAM20U0002849		Colour	WHITE
Odometer	177071 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2021		Inspection Date	13/08/2021
Survey held at	GLOCKEWERKE 21 KAKI BUKIT ROAD 4 #01-02 SYNERGY @ KB SINGAPORE 417810			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	