



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 1615J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (CONSISTENT)	NOT NECESSARY	996.00	-
1	BONNET LOGO -TOYOTA (CONSISTENT)	NOT NECESSARY	87.00	-
1	BONNET LOCK (CONSISTENT)	NOT NECESSARY	135.00	-
1	BONNET LOCK CATCH (CONSISTENT)	NOT NECESSARY	73.00	-
2	HEADLAMP L+R @\$1279.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CUT	2,558.00	672.00
2	HEADLAMP BRACKET L+R @\$125.00 (CONSISTENT)	N/S NOT NECESSARY / O/S DEFORMED	250.00	125.00
1	FRONT GRILLE ASSY (CONSISTENT)	NOT NECESSARY	427.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	592.00	592.00
1	FRONT BUMPER RETAINER RH (CONSISTENT)	NECESSARY	96.00	96.00
1	FRONT BUMPER REINFORCEMENT BAR (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	179.00	131.92
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	CRACKED	278.00	278.00
1	FRONT BUMPER FOG LAMP GARNISH RH (CONSISTENT)	CRACKED	179.00	179.00
1	FRONT FENDER RH (CONSISTENT)	BENT	884.00	786.90
1	FRONT FENDER SIGNAL LAMP RH (CONSISTENT)	NOT NECESSARY	82.00	-
1	FRONT FENDER COWLING RH (CONSISTENT)	TORN	219.00	154.43
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	1,296.00	-
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	324.00	-
1	FRONT ABSORBER RH (CONSISTENT)	NOT NECESSARY	528.00	-
1	FRONT LOWER ARM RH (CONSISTENT)	NOT NECESSARY	224.00	-
1	FRONT KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	425.00	-
1	FRONT KNUCKLE BEARING HUB RH (CONSISTENT)	NOT NECESSARY	183.00	-
1	FRONT BEARING HUB RH (CONSISTENT)	NOT NECESSARY	247.00	-
1	FRONT TIE ROD RH (CONSISTENT)	NOT NECESSARY	221.00	-
1	FRONT TIE ROD END RH (CONSISTENT)	NOT NECESSARY	161.00	-
1	FRONT DRIVE SHAFT RH (CONSISTENT)	NOT NECESSARY	1,913.00	-
1	FRONT STEERING RACK AND PINION ASSY (CONSISTENT)	NOT NECESSARY	1,395.00	-

Report Ref No. CC4/ASM21008469/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER LINK RH (CONSISTENT)	NOT NECESSARY	192.00	-
1	FRONT DOOR RH (CONSISTENT) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR SIDE MIRROR ASSY RH (CONSISTENT)	DISTORTED	709.00	630.20
1	FRONT DOOR SIDE MIRROR COVER RH (CONSISTENT)	TO REPAIR SEE LABOUR	75.00	-
1	WIPER WASHER TANK (CONSISTENT)	DEFORMED	150.00	150.00
	LESS 25% DISCOUNT		-3,839.50	-948.86
			11,518.50	2,846.59
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	FRONT FENDER COWLING CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	10.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT RIM RH (SN) (CONSISTENT)	CUT	2,500.00	600.00
1	FRONT TYRE RH (SN) (CONSISTENT)	NOT NECESSARY	800.00	-
			3,700.00	640.00
	<u>LABOUR</u>			
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND FRONT DOOR SIDE MIRROR COVER RH .		1,400.00	400.00
	SPRAY PAINT ON AFFECTED AREAS .		1,400.00	700.00
	TO CHECK WIRING AND HEADLAMP FOCUS .		150.00	30.00
	TO CHECK WHEEL ALIGNMENT AND ADJUST .		250.00	80.00
	TO RNR UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO CHECK WHEEL BALANCING.		250.00	30.00
	TO UNLOAD AND UPHOLSTERY .	NOT NECESSARY	400.00	-
	TO CHECK WATER LEAK .	NOT NECESSARY	150.00	-
	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS.	NOT NECESSARY	300.00	-
	TO RNR FRONT RADIATOR .	NOT NECESSARY	250.00	-
	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS.	NOT NECESSARY	600.00	-
	TO PERFORM RUST PROOFING.		400.00	30.00

Report Ref No. CC4/ASM21008469/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RNR HORN AND TEST FUNCTION.	NOT NECESSARY	150.00	-
			5,950.00	1,270.00
GRAND TOTAL			21,168.50	4,756.59
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CC4/ASM21008469/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.