

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008471/KPA3Q2**Date:** 05/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800027662
Claimant Vehicle No :	SJM3146G	Insured Vehicle No :	GBH2204A
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	3748648670SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3146G	Engine No:	4G18JY9868
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSNCS3A9U002022
Reg. Date:	29/12/2008 (Man. Year: 2008)	Odometer:	380236 km
Colour:	Metallic Black		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,684.70	4,200.70	484.00	10.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	2,020.00	300.00	12.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,004.70	6,220.70	784.00	11.19
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	7,004.70	4,950.00	2,054.70	29.33
+ GST 7.00/7.00% (S\$)	490.33	346.50	143.83	29.33
Nett Amount (S\$)	7,495.03	5,296.50	2,198.53	29.33
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,098.50		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment:	12/08/2021	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	13/08/2021	Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A
Estimated Period of Repair:	7.0 days	Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	697.00 FN	*697.00 FN
2	1		*REAR BUMPER LOWER SKIRT	Bent	668.00 FN	*668.00 FN
3	2		*REAR BUMPER SIDE RETAINER	Distorted	202.00 FN	*202.00 FN
4	1		*REAR BUMPER CENTRE INN BEAM	Bent	209.00 FN	*209.00 FN
5	6		*REAR BUMPER CLIPS	Necessary	21.00 FN	*21.00 FN
6	1		*REAR BOOT	Bent	593.00 FN	*593.00 FN
7	1		*REAR BOOT INNER LOCK	Dented	69.00 FN	*69.00 FN
8	1		*REAR BOOT INNER RUBBER (50%)	Dented / Distorted	157.50 FS	*87.50 FS
9	1		*REAR BOOT LOGO	Necessary	55.00 FN	*55.00 FN
10	1		*REAR BOOT EMBLEM (MITSUBISHI)	Necessary	56.00 FN	*56.00 FN
11	1		*REAR BOOT EMBLEM (GLX)	Necessary	35.00 FN	*35.00 FN
12	1		*REAR NUMBER PLATE GARNISH	Warped	221.00 FN	*221.00 FN
13	2		*TAILLAMPS	O/S Cut / N/S Cracked	842.00 FN	*842.00 FN
14	6		*TAILLAMP INNER CLIPS	Necessary	30.00 FN	*30.00 FN
15	1		*REAR CENTRE PANEL	Bent	495.00 FN	*474.00 FN
16	1		*REAR CENTRE PANEL INNER TOP GARNISH	Mtg Distorted	176.00 FN	*176.00 FN
17	1		*REAR EXHAUST PIPE	Repair	439.00 FN	*- FN
18	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
					Sub Total (S\$)	5,165.50 4,635.50
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	480.80 434.80
					Total Parts (S\$)	4,684.70 4,200.70

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR BOOT & SPOILER ,LOWER SKIRT ,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCK & REPAIR REAR BOTH FENDERS ,REAR SPARE TYRE COMPARTMENT ,STRAIGHTEN REAR RH CHASSIS & REALIGN THE SAME	New	1,200.00	1,000.00
2	REMOVE & REFIX REVERSE ,EXHAUST & CHECK SYSTEM	New	60.00	60.00
3	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT ,REAR BOTH FENDERS ,REAR BOOT ,REAR BUMPER ,REAR LOWER SPOILER & REAR AFFECTED AREAS	New	1,000.00	900.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$)			2,320.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >