



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 1199U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,074.00	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	299.00	299.00
1	FRONT LOGO -HYUNDAI (CONSISTENT)	NECESSARY	129.00	38.00
2	HEADLAMP L+R @\$3034.90 (CONSISTENT)	N/S NOT NECESSARY / O/S CUT	6,069.80	1,756.40
2	HEADLAMP BRACKET L+R @\$41.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	82.00	41.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	499.70	499.70
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	179.00	-
2	FRONT BUMPER SIDE GARNISH L+R (CONSISTENT)	NOT NECESSARY	144.00	-
2	FRONT BUMPER FOG LAMP L+R (CONSISTENT)	NOT NECESSARY	670.00	-
2	FRONT BUMPER FOG LAMP GARNISH L+R @\$149.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	298.00	149.00
2	FRONT BUMPER RETAINER L+R @\$31.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	62.00	31.00
1	FRONT BUMPER REINFORCEMENT BAR (CONSISTENT)	BENT	695.50	481.20
1	FRONT BUMPER LOWER BEAM (CONSISTENT)	BENT	219.60	219.00
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	119.20	119.20
1	FRONT BUMPER UNDERCOVER (CONSISTENT)	TORN	169.00	169.00
2	FRONT FENDER COWLING L+R @\$96.60 (CONSISTENT)	N/S NOT NECESSARY / O/S TORN	193.20	96.60
1	FRONT SUPPORT PANEL (CONSISTENT)	CRACKED	949.00	715.20
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	CRACKED	129.00	129.00
1	FRONT BRAKE ASSIST SENSOR (CONSISTENT)	NOT NECESSARY	970.00	-
1	AIRCON CONDENSOR (CONSISTENT)	NOT NECESSARY	1,049.00	-
2	AIRCON CONDENSOR AIR GUIDE L+R (CONSISTENT)	NOT NECESSARY	144.00	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	1,970.00	-
1	RADIATOR COWLING (CONSISTENT)	NOT NECESSARY	970.00	-
1	FRONT HORN (CONSISTENT)	NOT NECESSARY	144.00	-

Report Ref No. CC4/ASM21008472/Tpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TOP AIR DUCT (CONSISTENT)	CRACKED	369.00	269.00
	LESS 20% DISCOUNT		-3,519.40	-1,002.46
			14,077.60	4,009.84
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BONNET INSULATOR CLIPS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT FENDER COWLING CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	10.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	20.00
			520.00	60.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF BONNET .		1,200.00	600.00
	SPRAY PAINT ON AFFECTED AREAS .		1,000.00	500.00
	TO CHECK WIRING AND HEADLAMP FOCUS.		150.00	30.00
	TO CHECK WIRING AND FOG LAMP FUNCTION .	NOT NECESSARY	150.00	-
	TO RNR INNER TRIM AND UPHOLSTERY .	NOT NECESSARY	400.00	-
	TO CHECK WATER LEAK .		150.00	-
	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS.		300.00	-
	TO RNR FRONT RADIATOR .	NOT NECESSARY	250.00	-
	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS.	NOT NECESSARY	600.00	-
	TO RNR FRONT PARKING SENSOR AND CHECK FUNCTION .	NOT NECESSARY	150.00	-
	TO PERFORM RUST PROOFING.	NOT NECESSARY	400.00	-
	TO RNR HORN AND TEST FUNCTION .	NOT NECESSARY	150.00	-
			4,900.00	1,130.00
	<b>GRAND TOTAL</b>		<b>19,497.60</b>	<b>5,199.84</b>

Report Ref No. CC4/ASM21008472/Tpa3q2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,150.00</b>
---	--	--	-----------------

Report Ref No. CC4/ASM21008472/Tpa3q2

**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.