

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008474/KUCN2**Date:** 09/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00163332000	
Claimant Vehicle No :	SLL3551B	Insured Vehicle No :	SJF914M	
Date of Loss:	10/08/2021	Nature of Claim:	TP	Claim No: SNM21D204429/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL3551B		Engine No:	L15B31200010
Make & Model:	HONDA JAZZ, 1.5 VTIR (A)		Chassis No:	JHMGK5750HX202394
Reg. Date:	22/02/2017 (Man. Year: 2017)		Odometer:	139812 km
Colour:	Metallic Silver			
Engine Capacity:	1498 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,404.40	2,679.39	725.01	21.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,520.00	430.00	22.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,354.40	4,199.39	1,155.01	21.57
+ GST 7.00/7.00% (\$\$)	374.81	293.96	80.85	21.57
Nett Amount (\$\$)	5,729.21	4,493.35	1,235.86	21.57

INSPECTION

Date of Assignment:	12/08/2021	K.kim Hin Auto Pte Ltd (Autocity) 160 Sin Ming Drive, #02-18/19/20/21, Sin Ming Autocity Singapore 575722
Date Inspected:	13/08/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2021)
Parts:	144	HONDA JAZZ 1.5 VTIR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL3551B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	492.00 FL	*492.00 FL
2	1		*REAR BUMPER SIDE RETAINER (LH/RH)	O/s Distorted	60.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE LOWER GARNISH (LH/RH)	Serviceable	90.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
5	1		*REAR END PANEL	Bent	352.20 FL	*352.20 FL
6	1		*REAR END PANEL TOP GARNISH	Distorted	100.00 FL	*100.00 FL
7	1		*O/S TAIL LAMP	Cut	237.00 FL	*237.00 FL
8	1		*SPARE TYRE SPONGE COMPARTMENT	Cracked	680.00 FL	*680.00 FL
9	1		*TAILGATE	Bent	769.30 FL	*769.30 FL
10	1		*TAILGATE LOCK	Repair	280.00 FL	*- FL
11	1		*TAILGATE JAZZ EMBLEM	Necessary	38.00 FL	*38.00 FL
12	1		*TAILGATE OUTER CHROME	Serviceable	195.60 FL	*- FL
13	1		*TAILGATE INNER TRIMBOARD	Serviceable	189.80 FL	*- FL
14	1		*TAILGATE GLASS MOULDING	Necessary	150.00 FL	*150.00 FL
15	1		*TAILGATE INNER HANDLE POCKET	Dented	63.40 FL	*63.40 FL
16	1		*REAR BUZZER	Cracked	34.40 FL	*34.40 FL
17	1		*TAILGATE WEATHERSTRIP (50%)	Distorted/Dented	97.84 FS	*61.15 FS
18	1		*REAR BUMPER L PLATE BRACKET	Not Necessary	60.00 FS	*- FS
19	2		*TAILGATE 8 & 0 REFLECTIVE STICKER	Necessary	20.00 FS	*20.00 FS
20	1		*TAILGATE THANK YOU FOR YOUR PATIENCE	Necessary	150.00 FS	*150.00 FS
21	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*TAILGATE GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,158.54	3,276.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	754.14	597.06
Total Parts (\$\$)	3,404.40	2,679.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	680.00	600.00
2	TO REMOVE AND RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
3	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING,ROOF LINING,SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	180.00	60.00
4	TOAPPLY UNDERSEALING	New	80.00	60.00
5	TO TRANSFER TAILGATES FITTINGS	New	80.00	60.00
6	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	780.00	600.00
7	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION	New	30.00	20.00
Gross Labour Cost (\$\$)			1,950.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >