

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008476/BUF3N2**Date:** 06/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29075764MKF
Claimant Vehicle No :	SJN6981L	Insured Vehicle No :	YP4091E
Date of Loss:	12/08/2021	Nature of Claim:	TP
		Claim No:	637490

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN6981L	Engine No:	R18A1784892
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61076563
Reg. Date:	25/02/2009 (Man. Year: 2008)	Odometer:	349529 km
Colour:	Blue		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,379.04	2,130.64	4,248.40	66.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	800.00	1,240.00	60.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,419.04	2,930.64	5,488.40	65.19
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	8,419.04	2,350.00	6,069.04	72.09
+ GST 7.00/7.00% (S\$)	589.33	164.50	424.83	72.09
Nett Amount (S\$)	9,008.37	2,514.50	6,493.87	72.09

INSPECTION

Date of Assignment:	12/08/2021	
Date Inspected:	13/08/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2021)
Parts: M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN6981L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	723.90 FL	*638.90 FL
2	1		*BONNET RH HINGE	Not Damaged	78.60 FL	*- FL
3	1		*BONNET LH HINGE	Not Damaged	78.60 FL	*- FL
4	1		*BONNET LOCK	Not Damaged	56.80 FL	*- FL
5	1		*BONNET HEAT INSULATOR	Not Damaged	160.80 FL	*- FL
6	1		*BONNET INNER RUBBER SEAL	Not Damaged	101.20 FL	*- FL
7	1		*FRONT BUMPER	Broken	695.60 FL	*520.00 FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	22.40 FL	*22.40 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	22.40 FL	*22.40 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	248.80 FL	*185.00 FL
11	1		*FRONT GRILLE	Broken	238.10 FL	*238.10 FL
12	1		*FRONT GRILLE CHROME MOULDING	Dislodged	230.30 FL	*160.00 FL
13	1		*FRONT GRILLE EMBLEM	Not Damaged	36.50 FL	*- FL
14	1		*RH HEADLAMP ASSY	Broken	695.40 FL	*380.00 FL
15	1		*RH HEADLAMP LOWER BRACKET	Broken	66.80 FL	*39.50 FL
16	1		*LH HEADLAMP LOWER BRACKET	Broken	66.80 FL	*39.50 FL
17	1		*SUPPORT PANEL	Not Damaged	566.20 FL	*- FL
18	1		*SUPPORT PANEL TOP GARNISH	Not Damaged	167.70 FL	*- FL
19	1		*RADIATOR ASSY	Not Damaged	1,764.50 FL	*- FL
20	1		*AIRCON CONDENSER	Not Damaged	1,007.00 FL	*- FL
21	1		*SET BONNET INNER HEAT INSULATOR CLIPS	Not Necessary	70.00 FS	*- FS
22	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
23	1		*SET SUPPORT PANEL TOP COVER CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*RADIATOR COOLANT (NPA)	Not Necessary	0.00 FS	*- FS
25	1		*LH HEADLAMP ASSY	Broken	695.40 FL	*380.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,923.80	2,655.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,544.76	525.16
Total Parts (\$\$)	6,379.04	2,130.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	800.00	400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	900.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	50.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR.TO REFILL AIRCON GAS	New	200.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY.HOSES AND FAN ASSY TO ASSIST REPAIR.TO REFILL COOLANT	New	20.00	0.00
Gross Labour Cost (\$\$)			2,040.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >