

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 11 Nov 2021

Preliminary Advice

Insured Vehicle No	: YP4091E	Accident Date	: 12/08/2021
TP Vehicle No	: SJN6981L	Assignment Date	: 12/08/2021
Make	: HONDA STREAM	Est. Duration of Repair	: 5
Date of Inspection	: 13/08/2021		
Inspection At	: BIFROST AUTO PTE LTD (KAKI BUKIT) 8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,419.04
Revised Amount	:S\$	2,930.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,930.64
 Lump Sum Repair	 :S\$	 2,350.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	23,046.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,954.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.