



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3287U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	752.20	-
1	FRONT DOOR RH	BENT / WARPED	1,754.50	1,754.50
1	FRONT DOOR INNER LOCK RH	SERVICEABLE	302.50	-
1	FRONT DOOR WEATHERSTRIP RH	RIPPED / NECESSARY	195.80	195.80
1	FRONT DOOR WINDOW GEAR REGULATOR RH	SERVICEABLE	215.50	-
1	FRONT DOOR INNER BOARD RH	SERVICEABLE	658.90	-
1	FRONT DOOR WINDOW MOTOR RH	SERVICEABLE	265.00	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,654.80	-
2	REAR DOOR HINGE @\$75.00	SERVICEABLE	150.00	-
1	REAR DOOR WEATHERSTRIP RH	SERVICEABLE	195.80	-
1	REAR DOOR WINDOW GEAR REGULATOR RH	SERVICEABLE	215.50	-
1	REAR DOOR WINDOW MOTOR RH	SERVICEABLE	265.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,985.40	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	345.80	-
1	REAR CONTROL ARM RH	SERVICEABLE	322.00	-
1	REAR KNUCKLE ARM RH	SERVICEABLE	598.40	-
1	REAR KNUCKLE BEARING RH	SERVICEABLE	195.70	-
1	REAR KNUCKLE BEARING HUB RH	SERVICEABLE	233.00	-
	LESS 10% DISCOUNT		-1,030.58	-195.03
			9,275.22	1,755.27
<u>SPECIAL NETT ITEMS</u>				
2	DOOR SEALANT (SN)	SERVICEABLE	50.00	-
			50.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE, REPLACE, CUT & WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH, REAR DOOR RH AND REAR FENDER RH.		540.00	400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL (4 PANELS).		850.00	800.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	50.00	-
	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR RH.		90.00	60.00
	TRANSFER OF EXISTING REAR DOOR MECHANISM TO NEW DOOR RH.	NOT NECESSARY	90.00	-
	REMOVE AND REBUILT REAR UNDERCARRIAGE WORKS RH.	NOT NECESSARY	225.00	-
	CONDUCT WATER LEAK TEST FOR ASSOCIATED REPAIR WORKS.	NOT NECESSARY	67.50	-
	SPECIALIST CHARGES - WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY). (NPA)	NOT NECESSARY	-	-
			1,972.50	1,260.00
	GRAND TOTAL		11,297.72	3,015.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS3/INC21002426/Gqf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.