

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008482/APA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900256738
Claimant Vehicle No :	SLQ5095L	Insured Vehicle No :	GBB6971Z
Date of Loss:	20/07/2021	Nature of Claim:	TP
		Claim No:	3797631334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ5095L	Engine No:	G4LEHS159131
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Chassis No:	KNACC81CVH5087119
Reg. Date:	13/07/2017 (Man. Year: 2017)	Odometer:	402536 km
Colour:	White		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,641.40	2,094.50	7,546.90	78.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	550.00	2,510.00	82.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,701.40	2,644.50	10,056.90	79.18
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	12,701.40	2,100.00	10,601.40	83.47
+ GST 7.00/7.00% (S\$)	889.10	147.00	742.10	83.47
Nett Amount (S\$)	13,590.50	2,247.00	11,343.50	83.47
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,583.45		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment:	12/08/2021		
Date Inspected:	16/08/2021	Inspected At:	Xin Hua Workshop Pte Ltd 8 KAKI BUKIT AVE 4 #04-07 Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	688.00 FL	*688.00 FL
2	1		*FRONT BUMPER LOWER	Not Necessary	387.00 FL	*- FL
3	1		*FRONT BUMPER SIDE BRACKET	Cracked	25.00 FL	*25.00 FL
4	1		*FRONT BUMPER UPPER SUPPORT GARNISH	Cracked	185.00 FL	*185.00 FL
5	1		*FRONT BUMPER TOWING COVER	Not Necessary	48.00 FL	*- FL
6	1		*FRONT BUMPER LOGO	Necessary	85.00 FL	*85.00 FL
7	2		*FRONT BUMPER FOG LAMP	Not Necessary	388.00 FL	*- FL
8	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	150.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER LOWER GARNISH	Not Necessary	56.00 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	98.00 FL	*- FL
11	2		*FRONT BUMPER SIDE RETAINER	Necessary	54.00 FL	*54.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	296.00 FL	*- FL
13	1		*FRONT BUMPER SPONGE	Cracked	127.00 FL	*127.00 FL
14	2		*FRONT BUMPER INNER COWLING	Not Necessary	254.00 FL	*- FL
15	1		*FRONT RADAR SENSOR	Not Necessary	1,685.00 FL	*- FL
16	1		*HEAD LAMP	N/S Cracked	1,138.00 FL	*569.00 FL
17	2		*HEAD LAMP LOWER BRACKET	Not Necessary	72.00 FL	*- FL
18	1		*CENTER GRILLE	Cut	296.00 FL	*296.00 FL
19	1		*CENTER GRILLE RING (CHROME)	Cut	176.00 FL	*176.00 FL
20	1		*BONNET	Not Necessary	873.00 FL	*- FL
21	2		*BONNET HINGE	Not Necessary	202.00 FL	*- FL
22	1		*BONNET INNER RUBBER	Not Necessary	48.00 FL	*- FL
23	1		*BONNET LOCK	Not Necessary	114.00 FL	*- FL
24	2		*BONNET STOPPER	Not Necessary	38.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Not Necessary	597.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL LOWER GARNISH	Not Necessary	152.00 FL	*- FL
27	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	78.00 FL	*- FL
28	1		*AIR CON CONDENSER	Not Necessary	796.00 FL	*- FL
29	1		*RADIATOR	Not Necessary	894.00 FL	*- FL
30	2		*RADIATOR TOP BRACKET	Not Necessary	48.00 FL	*- FL
31	1		*AIR DUCT	Not Necessary	98.00 FL	*- FL
32	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*60.00 FS
33	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
34	1		*SET CENTER GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
35	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
36	1		*SET FRONT SUPPORT PANEL LOWER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
37	1		*SET AIR CON CONDENSER SIDE GARNISH CLIP	Not Necessary	80.00 FS	*- FS
38	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,656.00	2,315.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,014.60	220.50
Total Parts (\$)	9,641.40	2,094.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	250.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,060.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >