

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921
 Email: ryderautoworkshop@gmail.com
 Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBL249M
 Accident Date : 11/8/2021
 Location : LAVENDER STREET

TP China.
 Jusper.

Model: TOYOTA HIACE
 (22/2/2021)

3P: GBF7421S (CHINA TAIPIING)

GDH2012016665

| S/Nos | Qty | Description | List \$ | S/Nett \$ | Nett \$ |
|-----------------------|--------|---|--------------------------|---------------------|-------------|
| 1 | 1 pc | Rear bumper <i>reband</i> | 656.20 | ✓ | - |
| 2 | 2pcs | Rear bumper o/s & n/s retainer <i>Neu</i> | 182.70 | ✓ | - |
| 3 | 2pcs | Rear bumper screw <i>Neu</i> | - | 20.00 | ✗ |
| 4 | 10 pcs | Rear bumper clips <i>Neu</i> | - | 30.00 | ✓ |
| 5 | 1 pc | Rear end panel outer <i>Dented.</i> | 594.60 | ✓ | - |
| 6 | 1 pc | Rear end panel inner <i>Repl</i> | 613.50 | ✗ | - |
| 7 | 1 pc | Rear tail-gate <i>Dented</i> | 2,425.90 2150 | ✗ | - |
| 8 | 1 pc | Rear tail-gate weatherstrip <i>Neu</i> | 420.00 | ✓ | - |
| 9 | 1 pc | Rear tail-gate emblem <i>Neu</i> | 82.00 | ✓ | - |
| 10 | 1 pc | Rear tail-gate lock <i>Repl.</i> | 392.00 282 | ✓ | - |
| 11 | 1 pc | Rear tail-gate catch <i>Neu</i> | 140.60 | ✓ | - |
| 12 | 1 pc | Rear windscreen molding <i>Neu</i> | - | 120.00 | ✓ |
| 13 | 1 pc | Rear windscreen sealant <i>Neu</i> | - | 80.00 60 | - |
| 14 | 1 pc | Rear tail-gate 70 KMPH emblem <i>Neu</i> | - | 15.00 | ✓ |
| 15 | 1 pc | Rear Toyota HIACE emblem <i>Neu</i> | - | 60.00 | ✓ |
| 16 | 1 pc | Rear reg. no. plate <i>Neu</i> | - | 35.00 | ✓ |
| 17 | 1 pc | Rear reverse sensor <i>Damaged</i> | - | 250.00 | 200 |
| XXXXXXXXXX | | | Sub-Total: | 5,507.50 | 610.00 0.00 |
| XXXXXXXXXX | | | | 25% | 0% 10% |
| XXXXXXXXXX | | | After Less %: | 4,130.63 | 610.00 0.00 |
| Labour | | | | | |
| 1 | | To remove and replace rear damaged parts, straighten & welding. | 1,000.00 | 800 800 | |
| 2 | | To spray painting. | 800.00 500 | | |
| 3 | | To remove & refit rear windscreen | 140.00 | 120 | |
| 4 | | To check wiring. | 100.00 30 | | |
| 5 | | To re-seal anti-rust. | 150.00 60 | | |
| | | | Sub-Total: | 2,190.00 | |
| | | | Total: | 6,930.63 | |
| | | | After Less 20%: | 5,544.50 | |

3947.50
 2960.62
 S.N: 485

Admin Lij
 H/S 12/08/21.
 05 days.
 Supplementary: 285.75
 total: 5241.37.
 H/S: 4.11K.

4.11K

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

GBL249M Supplementary.

Rees Bumper Reinforcement ^{Dented} 265 ✓

Rees Bumper Lower Bracket x 4.
Zent.

$29 \times 4 = 116$ ✓

Supplementary: 381.

Len 25%: 285.75.