

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008485/ARS3Q2
Date: 28/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900262849
Claimant Vehicle No :	SGU9787K	Insured Vehicle No :	SMR5570P
Date of Loss:	13/07/2021	Nature of Claim:	TP
		Claim No:	1524398561SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU9787K	Engine No:	1NZC541340
Make & Model:	TOYOTA AXIO, 1.5 (A)	Chassis No:	NZE1416025017
Reg. Date:	30/05/2007 (Man. Year: 2007)	Odometer:	174822 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,004.27	2,694.55	12,309.72	82.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,490.00	1,420.00	5,070.00	78.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,494.27	4,114.55	17,379.72	80.86
Approved Total (Overridden) (S\$)		2,600.00		

(S\$)	21,494.27	2,600.00	18,894.27	87.90
+ GST 7.00/7.00% (S\$)	1,504.60	182.00	1,322.60	87.90
Nett Amount (S\$)	22,998.87	2,782.00	20,216.87	87.90
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,082.00		

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 5.0 days

Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	723.50 FL	*- FL
2	1		*FRT WIPER GARNISH	Not Necessary	423.80 FL	*- FL
3	1		*FRT WIPER GARNISH SIDE RUBBER	Not Necessary	58.00 FL	*- FL
4	1		*FRT HEADLAMP RH	Cut	605.80 FL	*605.80 FL
5	1		*FRT HEADLAMP CLIP	Necessary	30.00 FL	*10.00 FL
6	1		*FRT GRILLE ASSY	Not Necessary	456.20 FL	*- FL
7	1		*FRT BUMPER	Distorted	532.60 FL	*532.60 FL
8	1		*FRT BUMPER SIDE RETAINER RH	Not Necessary	68.90 FL	*- FL
9	1		*FRT BUMPER SIDE RETAINER LH	Not Necessary	68.90 FL	*- FL
10	1		*FRT BUMPER REINFORCEMENT	Not Necessary	345.30 FL	*- FL
11	1		*FRT BUMPER FOG LAMP COVER RH	Not Necessary	65.30 FL	*- FL
12	1		*FRT BUMPER LOW COVER	Not Necessary	205.80 FL	*- FL
13	1		*FRT FENDER RH	Dented	485.60 FL	*485.60 FL
14	1		*FRT FENDER SIGNAL LAMP RH	Not Necessary	95.20 FL	*- FL
15	1		*FRT FENDER QUARTER GARNISH RH	Not Necessary	67.10 FL	*- FL
16	1		*FRT FENDER INNER SHIELD RH	Not Necessary	152.20 FL	*- FL
17	1		*FRT FENDER ENCLOSURE RH	Not Necessary	97.20 FL	*- FL
18	1		*FRT SHOCK ABSORBER RH	Not Necessary	386.50 FL	*- FL
19	1		*FRT SHOCK ABSORBER TOP MOUNTING RH	Not Necessary	155.20 FL	*- FL
20	1		*FRT LOW ARM RH	Not Necessary	397.50 FL	*- FL
21	1		*FRT LOW ARM BALL JOINT RH	Not Necessary	174.50 FL	*- FL
22	1		*FRT GRILLE CROSSMEMBER	Not Necessary	1,612.00 FL	*- FL
23	1		*FRT KNUCKLE ARM RH	Not Necessary	468.60 FL	*- FL
24	1		*FRT WHEEL HUB BEARING RH	Not Necessary	385.20 FL	*- FL
25	1		*FRT STABILIZER LINK RH	Not Necessary	160.50 FL	*- FL
26	1		*FRT SIDE MIRROR RH	Not Necessary	542.30 FL	*- FL
27	1		*FRT DOOR RH	Dented	1,245.80 FL	*1,245.80 FL
28	1		*FRT DOOR STICKER RH	Necessary	139.60 FL	*139.60 FL
29	1		*FRT DOOR LOCK RH	Not Necessary	345.80 FL	*- FL
30	1		*FRT DOOR SPEAKER RH	Not Necessary	145.20 FL	*- FL
31	1		*FRT DOOR INNER TRIM RH	Not Necessary	854.60 FL	*- FL
32	1		*FRT DOOR GLASS RH	Not Necessary	687.50 FL	*- FL
33	1		*FRT DOOR GLASS REGULATOR RH	Not Necessary	589.60 FL	*- FL
34	1		*FRT DOOR GLASS REGULATOR MOTOR RH	Not Necessary	546.30 FL	*- FL
35	1		*FRT DOOR WEATHERSTRIP RH	Not Necessary	185.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RR DOOR RH	Not Necessary	1,258.90 FL	*- FL
37	1		*RR DOOR STICKER RH	Not Necessary	137.80 FL	*- FL
38	1		*RR DOOR INNER TRIM RH	Not Necessary	854.70 FL	*- FL
39	1		*RR DOOR WEATHERSTRIP RH	Not Necessary	185.20 FL	*- FL
40	1		*RR FENDER RH	Not Necessary	1,245.80 FL	*- FL
41	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
42	10		*FRT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
43	5		*FRT GRILLE CLIP	Not Necessary	30.00 FS	*- FS
44	10		*FRT FENDER INNERSHIELD CLIP	Not Necessary	60.00 FS	*- FS
45	1		*FRT SPORT RIM RH	Cut	700.00 FS	*400.00 FS
46	1		*FRT TYRE RH	Not Necessary	250.00 FS	*- FS
47	1		*RR SPORT RIM RH	Not Necessary	700.00 FS	*- FS
48	1		*RR TYRE RH	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,300.70	3,449.40
- List Item Discount on L Items 25.00/25.00% (\$)	4,296.43	754.85
Total Parts (\$)	15,004.27	2,694.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,000.00	600.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,FRT BUMPER ,FRT FENDER RH ,FRT DOOR RH ,RR DOOR RH ,RR FENDER RH	New	2,000.00	600.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	30.00
5	TO REMOVE AND REFIT AIRCON CONDENSOR ,VACUUM ,REFILL AND CHECK AIR CON GAS SYSTEM	New	180.00	0.00
6	TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	New	300.00	0.00
7	TO CONDUCT 4 WHEEL ALIGNMENT	New	160.00	80.00
8	TO CONDUCT RESET OF ENGINE LIGHT ON	New	250.00	0.00
9	TO CONDUCT RESET OF ABS LIGHT ON	New	250.00	0.00
10	TO REFOCUS HEADLAMP	New	80.00	0.00
11	TO CONDUCT TRANSFER FRONT DOOR MECHANISM TO NEW DOOR PANEL	New	250.00	80.00
12	TO APPLY DOOR SEALANT TO DOOR	New	160.00	0.00
13	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	160.00	0.00
14	TO CONDUCT TRANSFER REAR DOOR MECHANISM TO NEW DOOR PANEL	New	250.00	0.00
15	REMOVE AND REPLACE RHR UNDER CARRIAGE PARTS	New	250.00	0.00
Gross Labour Cost (\$\$)			6,490.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >