



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 1791D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET (NO DAMAGED)	NOT NECESSARY	938.00	-
2	FRONT BONNET HINGES (NO DAMAGED)	NOT NECESSARY	116.60	-
2	FRONT HEADLAMPS	O/S CRACKED	5,116.00	2,558.00
1	FRONT GRILLE	NOT NECESSARY	356.00	-
1	FRONT BUMPER	TORN	1,339.78	1,339.78
1	SET FRONT BUMPER CLIP	NECESSARY	60.00	60.00
1	FRONT BUMPER O/S FOG LAMP	CRACKED	210.00	210.00
1	FRONT BUMPER O/S FOG LAMP COVER	TWISTED	68.53	68.53
1	FRONT BUMPER INNER SPONGE	TORN	72.00	72.00
1	FRONT BUMPER REINFORCEMENT (NO DAMAGED)	NOT NECESSARY	692.00	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	154.00	154.00
1	FRONT BUMPER O/S SIDE LAMP	CRACKED	195.00	195.00
1	FRONT BUMPER TOW HOOK COVER	DEFORMED	55.00	55.00
1	FRONT BUMPER UNDERCOVER	TORN	295.00	295.00
1	FRONT BUMPER LOGO	NECESSARY	88.00	88.00
2	FRONT FENDERS	TO REPAIR SEE LABOUR	1,866.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,266.80	-
	LESS 25% DISCOUNT		-3,222.18	-1,273.83
			9,666.53	3,821.48
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
			50.00	-
<b><u>LABOUR</u></b>				
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT AIR-CON CONDENSER, VACUUM. REFILL GAS AND CONDUCT LEAKAGE TEST.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	180.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT FENDERS AND FRONT SUPPORT PANEL.		1,600.00	300.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	400.00
			3,540.00	720.00
<b>GRAND TOTAL</b>			<b>13,256.53</b>	<b>4,541.48</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS3/INC21005484/Uuf3e2-1

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.