

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Lima Limo Transport services

: 17 May 2021

C/o: Fei Auto

Our ref

: FEI/05/2101/TP

25 Kaki Bukit Road 4

#03-33 Synergy@KB, Singapore 417800

Accident Date

: 03 May 2021

Type of Survey: Third Party

Inspection Date Repairer Name

: 05 May 2021

: Fei Auto

25 Kaki Bukit Road 4

#03-33 Synergy@KB, Singapore 417800

PARTICULARS OF VEHICLE

Registration No

: SKP 1791 D

Year / Capacity:

:

2014 / 1797 cc

Make / Model

: Toyota Prius

Colour

White

Chassis No Engine No

: ZVW400009083 : 2ZRD290026

Mileage

551830

CONDITION OF TYRES

		Make	Size	Thread Balance	D!
Front Nearside	;	Firenza	215/60 R16	5 mm	Rim
Front Offside	:	Firenza	215/60 R16	5 mm	Sport
Rear Nearside	:	Firenza	215/60 R16	5 mm	Sport
Rear Offside	:	Firenza	215/60 R16	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front portion. (Details refer to the photographs attached)

Enclosed number of photographs:

83 copies

24205

#### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

#### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$8,800.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

4/5 3600 Submit 4 mgs.

## C L APPRAISER PTE LTD

Vehicle Registration No.: SKP 1791 D

Our Ref No .:

FEI/05/2101/TP

Qty	Description	Conditions		Repairer's Estimate	Revised Amount
	SPARE PARTS - LIST ITEMS				
1	Front bonnet (No Daged)	Damage	\$	938.00	\$ 938.00 >
2	Front bonnet hinges (Named)	Necessary	\$	116.60	\$ 116.60
2	Front headlamps 2518 0/5 cne	Damage	\$	5,116.00	\$ 5,116.00
1	Front grille	Damage	\$	356.00	\$ 356.00
1	Front bumper 7.00	Damage	\$	1,339.78	\$ 1,339.78
1	Front bumper clip (1 set)	Necessary	\$	60.00	\$ 60.00 _
1	Front bumper o/s fog lamp CM	Damage	\$	210.00	\$ 210.00
1	Front bumper o/s fog lamp cover 1M	Damage	\$	68.53	\$ 68.53 -
1	Front bumper inner sponge	Damage	\$	72.00	\$ 72.00
1	Front bumper reinforcement No Saled	Damage N	y2	692.00	\$ 692.00
2	Front bumper side retainers		\$	154.00	\$ 154.00_
1	Front bumper o/s side lamp	Damage	\$	195.00	\$ 195.00_
1	Front bumper tow hook cover	Damage	\$	55.00	\$ 55.00
1	Front bumper undercover 70.0	Damage	\$	295.00	\$ 295.00
1	Front bumper logo	Necessary	\$	88.00	\$ 88.00_
2	Front fenders	Repair	\$	1,866.00	×
1	Front support panel	Damage	\$	1,266.80	\$ 1,266.80
	•		\$	12,888.71	\$ 11,022.71
		Less 25%	\$	3,222.18	\$ 2,755.68
	Total Cost - List Items		\$	9,666.53	\$ 8,267.03
	SPECIAL NETT ITEMS				· ·
1	Front number plate with holder	\ Damage	\$	50.00	\$ 50.00
1	Total Cost - Special Nett items		S	50.00	\$ 50.00

Total cost of parts

\$ 9,716.53	\$ 8,317.03

# C L APPRAISER PTE LTD

Vehicle Registration No.: SKP 1791 D

Our Ref No.:

FEI/05/2101/TP

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	9,716.53	\$	8,317.03	
	<u>LABOUR</u>					
1	To check wiring, lighting and resetting headlamps	\$	80.00	\$	50.00	
	focusing.		100.00	¢	120.00	X
2	To remove and refit air-con condenser, vacuum, refill gas and conduct leakage test.	\$	180.00			
3	To apply undercoating on repaired and replaced panel.	\$	180.00	\$	120.00	X
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the	\$	1,600.00	\$	1,250.00	302
	accident.					(1,0
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,500.00	\$	1,100.00	4C
	GRAND TOTAL	\$	13,256.5	3 \$	10,957.03	_

5095.31 2571.48 4541.48 3633



Vehicle Registration No.: SKP 1791 D

Our Ref No .:

FEI/05/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 8,800.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. A Automotive Appraiser