

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008486/GQF3E2**Date:** 30/09/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001791941

Claimant Vehicle No : SJJ9957J**Insured Vehicle No :** SKR4623B

Date of Loss: 10/08/2021

Nature of Claim: TP Claim No: 261102

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJJ9957J**

Make & Model: HONDA FREED, 1.5 G (A)

Engine No: L15A2301075

Reg. Date: 30/09/2008 (Man. Year: 2008)

Chassis No: GB31001038

Colour: Blue

Odometer: 148875 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,775.20	14,917.15	24,858.05	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,750.00	3,810.00	16,940.00	81.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,525.20	18,727.15	41,798.05	69.06
Approved Total (Overridden) (S\$)		14,900.00		
(S\$)	60,525.20	14,900.00	45,625.20	75.38
+ GST 7.00/7.00% (S\$)	4,236.76	1,043.00	3,193.76	75.38
Nett Amount (S\$)	64,761.96	15,943.00	48,818.96	75.38

INSPECTION

Date of Assignment: 12/08/2021

Date Inspected: 19/08/2021 Inspected At:

56 Loyang Way #04-04

Repairer: AP Automotive Services Pte Ltd (HQ)

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2022)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ9957J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN MOULDING	Necessary	77.00 FL	*77.00 FL
2	1		*FRONT WIPER PANEL GARNISH	Cut	355.00 FL	*355.00 FL
3	2		*FRONT WIPER PANEL SIDE GARNISH L+R	Cut	260.00 FL	*30.00 FL
4	1		*BONNET	Buckled	711.00 FL	*711.00 FL
5	1		*BONNET INSULATOR	Not Necessary	175.00 FL	*- FL
6	2		*BONNET HINGE L+R	Bent	152.00 FL	*116.84 FL
7	1		*BONNET LOCK	Bent	144.00 FL	*144.00 FL
8	1		*BONNET RUBBER STRIP	Torn	28.00 FL	*28.00 FL
9	2		*HEADLAMP L+R	Cracked	3,640.00 FL	*1,300.00 FL
10	2		*HEADLAMP BRACKET L+R	Broken	78.00 FL	*78.00 FL
11	1		*FRONT GRILLE COMPLETE	Cut	785.00 FL	*237.50 FL
12	1		*FRONT GRILLE LOGO - HONDA	Necessary	28.00 FL	*28.00 FL
13	1		*FRONT BUMPER	Torn	841.00 FL	*562.10 FL
14	1		*FRONT BUMPER LOWER	Not Necessary	117.00 FL	*- FL
15	2		*FRONT BUMPER RETAINER L+R	Cut	50.00 FL	*50.00 FL
16	1		*FRONT BUMPER TOW COVER	Missing	28.00 FL	*28.00 FL
17	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	350.00 FL	*350.00 FL
18	1		*FRONT BUMPER UNDERCOVER	Deformed	110.00 FL	*110.00 FL
19	1		*FRONT FENDER L+R	N/S Repair / O/S Buckled	1,014.00 FL	*507.00 FL
20	1		*FRONT FENDER QUARTER WINDOW RH	Missing	285.00 FL	*285.00 FL
21	2		*FRONT FENDER QUARTER WINDOW MOULDING L+R	Not Necessary	116.00 FL	*- FL
22	1		*FRONT FENDER INNER PANEL RH	Buckled	295.00 FL	*295.00 FL
23	2		*FRONT FENDER COWLING L+R	Torn	250.00 FL	*250.00 FL
24	1		*FRONT WHEELHOUSE RH	Repair	375.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Bent	625.00 FL	*625.00 FL
26	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	328.00 FL	*- FL
27	1		*FRONT DOOR RH	Repair	888.00 FL	*- FL
28	2		*FRONT DOOR HINGE RH	Not Necessary	170.00 FL	*- FL
29	1		*FRONT DOOR CHECKER RH	Not Necessary	98.00 FL	*- FL
30	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	122.00 FL	*- FL
31	1		*FRONT DOOR INNER WEATHERSTRIP RH	Not Necessary	145.00 FL	*- FL
32	2		*A PILLAR L+R	Repair	1,542.00 FL	*- FL
33	1		*FRONT HORN	Cut	76.00 FL	*76.00 FL
34	1		*AIRCON CONDENSOR	Bent	747.00 FL	*747.00 FL
35	2		*AIRCON CONDENSOR AIRGUIDE L+R	Missing	150.00 FL	*150.00 FL
36	1		*AIRCON HIGH PRESSURE HOSE	Torn	178.00 FL	*178.00 FL
37	1		*AIRCON LOW PRESSURE HOSE	Torn	145.00 FL	*145.00 FL
38	1		*RADIATOR	Bent	1,355.00 FL	*1,355.00 FL
39	1		*RADIATOR COWLING	Broken	58.00 FL	*58.00 FL
40	1		*RADIATOR FAN BLADE	Broken	95.00 FL	*95.00 FL
41	1		*RADIATOR MOTOR	Not Necessary	322.00 FL	*- FL
42	1		*SUCTION PIPE	Bent	144.00 FL	*144.00 FL
43	1		*DISCHARGE PIPE	Bent	159.00 FL	*159.00 FL
44	1		*RADIATOR SPARE TANK	Deformed	48.00 FL	*48.00 FL
45	1		*AIR TEMPERATURE SENSOR	Not Necessary	77.00 FL	*- FL
46	1		*WIPER WASHER TANK	Deformed	75.00 FL	*75.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*ABS PUMP	Not Necessary	2,855.00 FL	*- FL
48	1		*AIR FILTER BOX	Broken	124.00 FL	*124.00 FL
49	1		*AIR FILTER HOSE	Not Necessary	85.00 FL	*- FL
50	1		*AIR FILTER BOX AIR DUCT	Missing	95.00 FL	*95.00 FL
51	1		*AIR FLOW SENSOR	Not Necessary	244.00 FL	*- FL
52	1		*AIR INTAKE MANIFOLD	Not Necessary	399.00 FL	*- FL
53	1		*AIR INTAKE MANIFOLD COOLER	Not Necessary	75.00 FL	*- FL
54	1		*AIRCON COMPRESSOR	Not Necessary	1,851.00 FL	*- FL
55	1		*BATTERY BRACKET	Not Necessary	55.00 FL	*- FL
56	1		*BATTERY TRAY	Not Necessary	48.00 FL	*- FL
57	1		*FUSE BOX	Broken	1,770.00 FN	*200.00 F
58	1		*AIR CLEANER BOX	Cracked	242.00 FL	*242.00 FL
59	2		*AIRBAG SENSOR L+R	Activated	252.00 FL	*252.00 FL
60	1		*AIRBAG ECU	Activated	850.00 FL	*850.00 FL
61	1		*ENGINE MOUNTING	Cracked	125.00 FL	*125.00 FL
62	1		*ENGINE TOP COVER	Not Necessary	221.00 FL	*- FL
63	1		*SET GEARBOX MOUNTING (2 SET)	Cracked (1Set Only)	424.00 FL	*212.00 FL
64	1		*FAN BELT	Not Necessary	120.00 FL	*- FL
65	1		*ALTERNATOR	Cracked	600.00 FL	*600.00 FL
66	1		*THERMOSTAT	Not Necessary	78.00 FL	*- FL
67	1		*BRAKE BOOSTER PUMP	Not Necessary	955.00 FL	*- FL
68	1		*BRAKE FLUID TANK	Not Necessary	211.00 FL	*- FL
69	1		*FRONT DRIVER SEATBELT	Activated	808.00 FL	*598.00 FL
70	1		*FRONT PASSENGER SEATBELT	Activated	808.00 FL	*598.00 FL
71	1		*FRONT STEERING WHEEL	Not Necessary	683.00 FL	*- FL
72	1		*FRONT STEERING AIRBAG	Activated	1,640.00 FL	*1,640.00 FL
73	1		*FRONT STEERING COIL	Not Necessary	299.00 FL	*- FL
74	1		*FRONT DASHBOARD	Cracked	977.00 FL	*977.00 FL
75	1		*FRONT DASHBOARD BRACKET	Not Necessary	855.00 FL	*- FL
76	1		*FRONT PASSENGER AIRBAG	Activated	2,236.00 FL	*2,236.00 FL
77	2		*FRONT AIRBAG SENSOR L+R	Repeated	252.00 FL	*- FL
78	2		*FRONT CHASSIS L+R	Not Necessary	1,352.00 FL	*- FL
79	1		*FRONT ABSORBER RH	Not Necessary	466.00 FL	*- FL
80	1		*FRONT LOWER ARM RH	Not Necessary	352.00 FL	*- FL
81	1		*FRONT KNUCKLE RH	Not Necessary	325.00 FL	*- FL
82	1		*FRONT KNUCKLE BEARING RH	Not Necessary	135.00 FL	*- FL
83	1		*FRONT BEARING HUB RH	Not Necessary	202.00 FL	*- FL
84	1		*FRONT DRIVE SHAFT RH	Not Necessary	978.00 FL	*- FL
85	1		*FRONT STEERING RACK AND PINION ASSY	Not Necessary	1,899.00 FL	*- FL
86	1		*FRONT TIE ROD RH	Not Necessary	95.00 FL	*- FL
87	1		*FRONT TIE ROD END RH	Not Necessary	90.00 FL	*- FL
88	1		*FRONT STABILIZER LINK RH	Not Necessary	77.00 FL	*- FL
89	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
90	1		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
91	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
92	1		*FRONT NUMBER PLATE	Cracked	100.00 FS	*40.00 FS
93	1		*FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS
94	1		*FRONT FENDER WINDOW SEALANT	Necessary	80.00 FS	*20.00 FS
95	1		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*30.00 FS
96	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
97	1		*FRONT DOOR INNER BOARD CLIPS	Not Necessary	80.00 FS	*- FS
98	1		*FRONT DOOR VISOR	Not Necessary	100.00 FS	*- FS
99	1		*RADIATOR COOLANT	Necessary	100.00 FS	*40.00 FS
100	1		*BRAKE FLUID	Not Necessary	100.00 FS	*- FS
101	1		*FRONT RIM RH	Not Necessary	3,000.00 FS	*- FS
102	1		*FRONT TYRE RH	Punctured	400.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) 48,579.00 18,506.44
- List Item Discount on L Items 20.00/20.00% (\$\$) 8,449.80 3,589.29

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- Nett Item Discount on N Items 20.00/0.00% (S\$)					354.00	0.00
Total Parts (S\$)					39,775.20	14,917.15
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	3,000.00	1,500.00
2	SPRAY PAINT ON AFFECTED AREAS	New	2,800.00	1,400.00
3	TO REPAIR FRONT CHASSIS }	New	1,200.00	250.00
4	TO RNR FRONT CHASSIS }	New	1,200.00	0.00
5	TO RNR FRONT WINDSCREEN	New	300.00	120.00
6	TO RNR REAR FENDER WINDOW	New	300.00	0.00
7	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
8	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
9	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS }	New	300.00	120.00
10	TO RNR FRONT RADIATOR }	New	250.00	0.00
11	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	60.00
12	TO RNR UNDERCARRIAGE	New	250.00	0.00
13	TO RNR FRONT AIRBAG }	New	800.00	200.00
14	TO RNR FRONT DASHBOARD }	New	800.00	0.00
15	TO RESET AIRBAG ECU DIAGNOSTIC }	New	800.00	50.00
16	TO RNR ENGINE ECU }	New	600.00	0.00
17	TO RNR FRONT SEATBELTS	New	1,200.00	0.00
18	TO RNR FRONT STEERING WHEEL	New	800.00	0.00
19	TO RNR FANBELT	New	200.00	0.00
20	TO RNR AIR CLEANER BOX	New	200.00	0.00
21	TO RNR AIR FILTER BOX	New	300.00	0.00
22	TO RNR AIR INTAKE MANIFOLD	New	400.00	0.00
23	TO RNR AIRCON COMPRESSOR	New	400.00	0.00
24	TO RNR ALTERNATOR	New	400.00	0.00
25	TO RNR ENGINE MOUNTING	New	600.00	0.00
26	TO RNR GEARBOX MOUNTING	New	600.00	0.00
27	TO CHECK WHEEL BALANCING	New	250.00	0.00
28	TO CHECK WATER LEAK	New	150.00	0.00
29	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	0.00
30	TO RNR FRONT RADIATOR	New	250.00	0.00
31	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
32	TO VACUUM AND CLEAR GLASSES	New	300.00	0.00
33	TO PERFORM RUST PROOFING	New	400.00	80.00
Gross Labour Cost (\$\$)			20,750.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >