

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD21008490/KRS3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNMC2019-00004167-01
Claimant Vehicle No :	SNA5157C	Insured Vehicle No :	FBL3129G
Date of Loss:	12/08/2021	Nature of Claim:	TP
			Claim No: 1202100004315

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA5157C		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	L15B6051357
Reg. Date:	26/06/2021 (Man. Year: 2021)	Chassis No:	GK82201124
Colour:	Metallic Pearl White	Odometer:	11176 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,068.40	888.00	2,180.40	71.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	610.00	650.00	51.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,328.40	1,498.00	2,830.40	65.39
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	4,328.40	1,200.00	3,128.40	72.28
+ GST 7.00/7.00% (S\$)	302.99	84.00	218.99	72.28
Nett Amount (S\$)	4,631.39	1,284.00	3,347.39	72.28
+ Car Rental (2.0 x S\$85.60/day) (S\$)		171.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,462.65		

INSPECTION

Date of Assignment:	13/08/2021	
Date Inspected:	24/08/2021	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Nov 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA5157C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH HEADLAMP	Serviceable	2,550.00 FL	*- FL
2	1		*FRONT BUMPER	Mtg Cracked	1,150.50 FL	*1,050.00 FL
3	20		*FRONT BUMPER CLIP	Necessary	100.00 FL	*60.00 FL
4	1		*FRONT BUMPER LH SIDE RETAINER	Serviceable	35.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,835.50	1,110.00
- List Item Discount on L Items 20.00/20.00% (S\$)	767.10	222.00
Total Parts (S\$)	3,068.40	888.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	60.00	10.00
2	SPRAY PAINTING	New	600.00	400.00
3	LABOUR CHARGES	New	600.00	200.00
Gross Labour Cost (\$)			1,260.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >