

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 88Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID EMBLEM-HYBRID	NOT NECESSARY	24.30	-
1	BOOT LID EMBLEM-IONIQ	NOT NECESSARY	31.30	-
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	CUT	155.00	155.00
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$41.45	NOT NECESSARY	82.90	-
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR SMART KEY ANTENNA	CRACKED	40.50	40.50
	LESS 20% DISCOUNT		-447.59	-344.89
			1,790.36	1,379.56
	NETT ITEMS			
1	BOOT LID COMFORTDELGRO (N)	NOT NECESSARY	35.00	-
1	BOOT LID 65521111 (N)	NOT NECESSARY	35.00	-
1	BOOT LID APPS (N)	NOT NECESSARY	40.00	-
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	REAR NO PLATE W/TRIM COVER (N)	MISSING	55.00	55.00
	LESS 10% DISCOUNT		-34.50	-23.50
			310.50	211.50
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,120.00	630.00
	GRAND TOTAL		3,220.86	2,221.06

Report Ref No. NS/INC21008492/T1vcn2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)		2,221.06
---	--	----------

Report Ref No. NS/INC21008492/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser