COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1802K

Make : HYUNDAI

Model : IONIQ(G2)

Date: 11/08/21

Insurance: NTUC

MVA: MS. LOKE YY



Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER .	***************************************		trac \$459.40
10	REAR BUMPER CLIPS			mer \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			dl \$451.25
1	REAR BUMPER LOWER CENTRE MOULDING			Se \$155.00
1	REAR BUMPER REINFORCEMENT			ny × \$394.80
1	FOG LAMP			\$201.50
2	RR BUMPER REINFORCEMENT STAY LH RH		\$138.10	~4× \$276.20
1	REAR BUMPER REFLECTOR LAMP RH			MX \$41.45
1	LICENCE LAMP			cut \$85.30
1	REAR BUMPER TOWING COVER			mi5 \$98.80
1	REAR PANEL			MX \$532.00
1	REAR PANEL GARNISH	,		ペリ ⋉ \$346.80
	signs A225 mis		/	
	Nor bringen underwere Cente SUB TOTAL LESS 20%		11.98.25	\$2,001.60
	LESS 20%		1 2000 10	\$400.32
	DISCOUNTED TOTAL	λ	1698.25	\$1,601.28
1	REAR BUMPER RUBBER MAT			M-\$50.00
	REAR NUMBER PLATE WITH TRIM COVER		-10%	
	REAR BUMPER REVERSE SENSOR		-10%	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	TENTE SENTENCE SENSON		252.50	\$275.00
	Labour Charge			350.
	PANEL BEATING			\$950.00
	SPRAY PAINTING CHARGE		110	\$50 \$500.00
	WIRING CHARGE		660	30 \$50.00
	REMOVE/REFIX REVERSE SENSOR			30. \$80.00
			2271-10	
	TOTAL LABOUR	-		\$1,580.00
	•		44/1800	
	ESTIMATE TOTAL	E	213/100	\$3,456.28
			a 2 days	
			()	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughin 17475749

11/6/21 C440

1/5 Money of for repair

tentph c/Mantonolum

220/14

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

ı(e: