



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7253E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT COVER	TO REPAIR SEE LABOUR	1,052.20	-
1	GRILLE ASSY-RADIATOR	CRACKED	1,480.00	1,480.00
1	SYMBOL MARK-H	NECESSARY	129.50	129.50
10	BUMPER COVER CLIP	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-536.74	-326.30
			2,146.96	1,305.20
	<u>NETT ITEMS</u>			
1	VEHICLE NUMBER PLATE FRON (N)	CRACKED	50.00	50.00
	LESS 10% DISCOUNT		-5.00	-5.00
			45.00	45.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BUMPER FRT COVER.		300.00	280.00
	SPRAYPAINT CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.		50.00	30.00
			650.00	560.00
	GRAND TOTAL		2,841.96	1,910.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,550.00

Report Ref No. NS/INC21008494/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.