

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008496/UBS3Q2
Date: 27/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SDL7899S	Insured Vehicle No :	SMM6406B
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDL7899S		
Make & Model:	TOYOTA CAMRY, 2.4 (A)	Engine No:	2ARU183819
Reg. Date:	23/12/2014 (Man. Year: 2014)	Chassis No:	MR053AK5004008500
Colour:	Black	Odometer:	151339 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,816.41	2,361.44	10,454.97	81.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,830.00	920.00	24.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,566.41	5,191.44	11,374.97	68.66
Approved Total (Overridden) (S\$)		4,150.00		

(S\$)	16,566.41	4,150.00	12,416.41	74.95
+ GST 7.00/7.00% (S\$)	1,159.65	290.50	869.15	74.95
Nett Amount (S\$)	17,726.06	4,440.50	13,285.56	74.95
+ Car Rental (5.0 x S\$180.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,347.95		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment: 13/08/2021

Date Inspected: 16/08/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Abwin Service Pte Ltd -(17 Kaki Bukit Road 4) (HQ)
 No.17 Kaki Bukit Road 4, #01-60 Bartley Biz Centre
 Singapore 417809

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
Parts:	143	TOYOTA CAMRY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDL7899S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	657.60 F	*581.10 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	110.50 F	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Bent	110.50 F	*110.50 FL
4	1		*REAR BUMPER BRACKET RH (NPA)	No such part	0.00 F	*- FL
5	1		*REAR BUMPER BRACKET LH (NPA)	No such part	0.00 F	*- FL
6	1		*BOOT LID	Repair	1,143.70 F	*- FL
7	1		*BOOT LID OUTER GARNISH	Not Necessary	433.60 F	*- FL
8	1		*BOOT LID INNER TRIM	Not Necessary	478.90 F	*- FL
9	1		*BOOT LID LOCK	Not Necessary	398.90 F	*- FL
10	1		*BOOT LID LOCK SENSOR (NPA)	Not Necessary	0.00 F	*- FL
11	1		*BOOT LID INNER HANDLE (NPA)	Not Necessary	0.00 F	*- FL
12	1		*BOOT LID WEATHERSTRIP	Twisted	194.70 F	*194.70 FL
13	1		*BOOT LID OUTER CHROME MOULDING	Not Necessary	433.60 F	*- FL
14	1		*REAR SMART BUZZER	Not Necessary	191.50 F	*- FL
15	1		*REAR END PANEL	Badly Dented	670.00 F	*670.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	310.60 F	*310.60 FL
17	1		*REAR EXTENSION PANEL (NPA)	No such part	0.00 F	*- FL
18	1		*SPARE TYRE TOP BOX	Not Necessary	209.10 F	*- FL
19	1		*SPARE TYRE PANEL	Crumpled / Buckled	818.10 F	*818.10 FL
20	1		*SPARE TYRE LOWER GARNISH	Not Necessary	403.10 F	*- FL
21	1		*REAR TOOLS COMPARTMENT	Not Necessary	168.53 F	*- FL
22	1		*REAR BUMPER REFLECTOR RH	Not Necessary	63.59 F	*- FL
23	1		*REAR BUMPER REFLECTOR LH	Cracked	63.59 F	*63.59 FL
24	1		*TAILGATE LAMP LH	Not Necessary	360.90 F	*- FL
25	1		*TAILGATE LAMP RH	Not Necessary	360.90 F	*- FL
26	1		*TAIL LAMP BRACKET RH	Not Necessary	21.40 F	*- FL
27	1		*TAIL LAMP BRACKET LH	Not Necessary	21.40 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT BUMPER	Repair	569.90 F	*- FL
29	1		*FRONT BUMPER RETAINER RH	Not Necessary	100.40 F	*- FL
30	1		*FRONT BUMPER RETAINER LH	Not Necessary	100.40 F	*- FL
31	1		*HEADLAMP RH (CRACKED)	Not Consistent With The Impact	1,294.60 F	*- FL
32	1		*FOG LAMP COVER RH	Not Necessary	68.20 F	*- FL
33	1		*HEADLAMP PANEL RH	Not Necessary	198.70 F	*- FL
34	1		*FRONT BUMPER REINFORCEMENT	Repair	399.50 F	*- FL
35	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
36	1		*TAILGATE SEALANT	Not Necessary	50.00 FS	*- FS
37	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
38	1		*SET REVERSE SENSOR	Shorted	1,400.00 FS	*200.00 FS
39	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
40	1		*FRONT BUMPER SENSOR	Not Necessary	380.00 FS	*- FS
41	10		*HEADLAMP CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*FRONT NUMBER PLATE WITH BRACKET	Not Necessary	50.00 FS	*- FS
43	1		*REAR BUMPER PLATE WITH BRACKET	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,816.41	3,048.59
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	687.15
Total Parts (\$\$)	12,816.41	2,361.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,500.00	1,400.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	1,200.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New	180.00	60.00
4	TO DISMANTLE ,REPLACE AND/OR REPAIR TAILGATE COMPONENTS	New	180.00	0.00
5	TO DISMANTLE ,REPLACE AND/OR REPAIR FRONTAL COMPONENTS	New	180.00	100.00
6	TO DISMANTLE ,REPLACE AND /OR REPAIR FRONT SENSOR & TESTING	New	120.00	0.00
7	TO DISMANTLE ,REPLACE AND/OR REPAIR REAR SENSOR & TESTING	New	120.00	50.00
8	TO CHECK WIRING ,CHECK LIGHTING & RESETTING HEADLAMP FOCUS	New	150.00	20.00
9	TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE CAMERA & TESTING	New	120.00	0.00
Gross Labour Cost (\$\$)			3,750.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >