



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8825T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR FENDER RH	BENT	1,768.30	1,768.30
1	REAR WHEEL HUB CAP RH	CUT	346.40	346.40
1	RR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-519.22	-427.34
			2,076.88	1,709.36
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF RR BUMPER COVER.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		700.00	500.00
	WIRING CHARGE.	NOT NECESSARY	60.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE & REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
			2,020.00	1,085.00
	<b>GRAND TOTAL</b>		<b>4,196.88</b>	<b>2,894.36</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,300.00</b>

Report Ref No. NS/INC21008498/T1ucn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.