

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET LOW Code: ASM 1.	ga3q2
AXA TOWERSINGAPORE 068811 ATTN:GARNET LOW Code: ASM Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SMK 3312T Veh. Inspected SLT 9318C Policy No. P2364483 Coverage (\$) 0.00 Claim No. S1M03FGR Excess (\$) 0.00 Assign From Assign Date 13/08/2021 Vehicle Particulars & Condition	
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SMK 3312T Veh. Inspected SLT 9318C Policy No. P2364483 Coverage (\$) 0.00 Claim No. S1M03FGR Excess (\$) 0.00 Assign From Assign Date 13/08/2021 2. Vehicle Particulars & Condition	
Insured Veh. SMK 3312T Veh. Inspected SLT 9318C	
Policy No. P2364483 Coverage (\$) 0.00 Claim No. S1M03FGR Excess (\$) 0.00 Assign From Assign Date 13/08/2021 Vehicle Particulars & Condition	
Claim No. S1M03FGR Excess (\$) 0.00 Assign From Assign Date 13/08/2021 2. Vehicle Particulars & Condition	
Assign From Assign Date 13/08/2021 2. Vehicle Particulars & Condition	
2. Vehicle Particulars & Condition	
Make & Model TOYOTA SIENTA HYBRID c.c 1496	
1 1	
Engine No. HIDDEN Year of Reg. 2017	
Chassis No. NHP1707100069 Colour GREY	
Odometer 22549 KM Steering IN ORDER	
Brakes IN ORDER Modification SPORTS RIM	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 195/60 R15 GENERAL 6 mm	
L/H Front Tyre 195/60 R15 GENERAL 6 mm	
R/H Rear Tyre 195/60 R15 GENERAL 6 mm	
L/H Rear Tyre 195/60 R15 GENERAL 6 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 11/08/2021 Inspection Date 13/08/2021	
Survey held at AP AUTOMOTIVE SERVICES PTE LTD	
9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days	