

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21008505/KVF3E2

**Date:** 17/09/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29138251ATM
<b>Claimant Vehicle No :</b>	SMN3140G	<b>Insured Vehicle No :</b>	SLJ1849S
Date of Loss:	11/08/2021	Nature of Claim:	TP
		Claim No:	637508

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3140G	Engine No:	2NRX481899
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Chassis No:	MHFZ28H3500064649
Reg. Date:	31/07/2019 (Man. Year: 2019)	Odometer:	17300 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,120.97	2,829.35	3,291.62	53.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,460.00	1,490.00	50.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,070.97</b>	<b>4,289.35</b>	<b>4,781.62</b>	<b>52.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,070.97</b>	<b>3,400.00</b>	<b>5,670.97</b>	<b>62.52</b>

### INSPECTION

Date of Assignment:	16/08/2021	160 Sin Ming drive #08-16 Sin Ming AutoCity
Date Inspected:	17/08/2021 Inspected At:	575722
Estimated Period of Repair:	5.0 days	Repairer: Ja Autocare Pte Ltd (HQ)

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2021)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN3140G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	650.80 FL	*495.50 FL
2	1		*REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
3	2		*REAR BUMPER BRACKET	Repair	120.00 FL	*- FL
4	2		*REAR BUMPER RETAINER	Serviceable	100.00 FL	*- FL
5	1		*REAR BUMPER CENTRE PAD	Dented	350.80 FL	*235.80 FL
6	1		*REAR BUMPER CENTRE PAD REFLECTOR RH	Dented	120.50 FL	*120.50 FL
7	1		*REAR BUMPER CENTRE REFLECTOR	Serviceable	85.50 FL	*- FL
8	1		*REVERSE SENSOR SOCKET	Mtg Cracked	350.80 FL	*196.20 FL
9	1		*REAR PANEL OUTER	Bent	350.00 FL	*350.00 FL
10	1		*TAIL GATE	Bent	1,450.80 FL	*1,040.40 FL
11	1		*TAIL GATE RUBBER	Distorted / Dented	250.80 FL	*50.00 FL
12	1		*TAIL GATE CENTRE CHROME	Serviceable	320.50 FL	*- FL
13	1		*TAIL GATE LOCK	Dented	330.50 FL	*330.50 FL
14	1		*TAIL GATE INNER TRIM BOARD	Serviceable	380.00 FL	*- FL
15	1		*TAIL GATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
16	1		*TOYOTA LOGO	Necessary	85.00 FL	*85.00 FL
17	1		*SIENTA EMBLEM	Necessary	95.00 FL	*95.00 FL
18	1		*TAIL LAMP ASSY RH	Serviceable	550.80 FL	*- FL
19	1		*REAR WIPER MOTOR ASSY	Serviceable	980.50 FL	*- FL
20	1		*TAIL REMOTE RECEIVER	Dented	489.00 FL	*127.00 FL
21	1		*TAILLAMP PANEL TOP GARNISH	Distorted	320.00 FL	*219.90 FL
22	1		*REAR WINDSCREEN SEALANT AND CLIP	Necessary	100.00 FS	*60.00 FS
23	1		*REVERSE SENSOR	Dented	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,001.30</b>	<b>3,685.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,880.33	856.45
<b>Total Parts (\$\$)</b>	<b>6,120.97</b>	<b>2,829.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE UPHOLSTERY	New	150.00	60.00
2	TO CHECK WIRING	New	120.00	20.00
3	TO APPLY ANTI RUST CHEMICAL	New	140.00	60.00
4	TO DISMANTLE REAR WINDSCREEN GLASS	New	140.00	120.00
5	TO KNOCK OUT DENST ON AFFECTED AREAS AND RENEW PARTS	New	1,200.00	600.00
6	TO PUTTY & RESPRAY PAINTING	New	1,200.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,950.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >