

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21008514/EQF3E2

Date: 29/10/2021

REFERENCE

Insured/Claimant:	WONG SHAW PING	Policy No:	2070160416		
Date of Loss:	13/08/2021	Nature of Claim:	OD	Claim No:	4651048366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW6487P		
Make & Model:	CITROEN GRAND C4 SPACETOURER, 1.2 (A)	Engine No:	10XVAY1500442
Reg. Date:	30/11/2020 (Man. Year: 2019)	Chassis No:	VF73AHNSRKJ762009
Colour:	White	Odometer:	4595 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,637.20	5,376.80	1,260.40	18.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,745.00	4,585.00	1,160.00	20.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,382.20	9,961.80	2,420.40	19.55
+ GST 7.00/7.00% (S\$)	866.75	697.33	169.42	19.55
Nett Amount (S\$)	13,248.95	10,659.13	2,589.82	19.55

INSPECTION

Date of Assignment: 13/08/2021

Date Inspected: 13/08/2021 Inspected At:

Estimated Period of Repair: 10.0 days

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*RR QUARTR GLASS LH	Not Necessary	168.00 FL	*- FL
3	1		*RR QTR MOULDING LH	Necessary	381.00 FL	*381.00 FL
4	1		*REAR WING LH	Dented	2,057.00 FL	*2,057.00 FL
5	1		*REAR BUMPER	Repair	1,130.00 FL	*- FL
6	1		*REAR DOOR LH ASS	Dented	1,556.00 FL	*1,556.00 FL
7	1		*DOOR HINGE LH INF	Not Necessary	86.00 FL	*- FL
8	1		*DOOR HINGE LH SUP	Not Necessary	86.00 FL	*- FL
9	1		*DOOR STOP	Not Necessary	93.00 FL	*- FL
10	1		*REAR DOOR SEAL LH INFERIEUR	Necessary	112.00 FL	*112.00 FL
11	1		*REAR DOOR SEAL LH	Necessary	239.00 FL	*239.00 FL
12	1		*DECOR STRIP LH	Necessary	200.00 FL	*200.00 FL
13	1		*DOOR FIXINGS	Necessary	222.00 FL	*222.00 FL
14	1		*ALLOY WHEEL 6.5 J16 CH5-47	Cut	593.00 FL	*593.00 FL
15	1		*WINDOW OUTSIDE LH (Supplementary)	Bent	102.00 FL	*102.00 FL
16	1		*DOOR LOCK LH (Supplementary)	Broken	328.00 FL	*328.00 FL
17	1		*WINDOW LIFTER LH (Supplementary)	Bent	620.00 FL	*620.00 FL
18	1		*SIDE WINDOW LH (Supplementary)	Broken	286.00 FL	*286.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,289.00	6,716.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,651.80	1,339.20
Total Parts (\$\$)	6,637.20	5,376.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, REAR LH FENDER, REAR LH DOOR & AFFECTED AREA	New	3,000.00	2,500.00
2	PAINT WORK ON REAR BUMPER, REAR LH FENDER & REAR LH DOOR	New	1,140.00	1,140.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	80.00
4	TO TRANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL	New	150.00	120.00
5	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	150.00	120.00
6	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	150.00	-
7	REMOVE & REPLACE REAR LH QURTER GLASS	New	200.00	-
8	TO APPLY QUATER GLASS SEALANT	New	80.00	80.00
9	TO SUPPLY QUATER GLASS SOLAR FILM	New	160.00	80.00
10	PERFORM RUST PREVENTION	New	80.00	40.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
12	TO TRANSFER REAR LH RIM INCLUDING BALANCING	New	30.00	30.00
13	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	60.00	50.00
14	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	225.00	225.00
15	TO APPLY BODY SEALANT	New	80.00	-
Gross Labour Cost (\$\$)			5,745.00	4,585.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >