



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 13.08.2021
Emailed : 08.10.2021, 11.15am
Date Survey : 13.08.2021

VEHICLE NO : SMW 6487 P
MODEL : CITROEN GRAND C4 SPACETOURE 1.2
WIP : 16817

Material	:	\$	5,356.80
Labour	:	\$	4,605.00
Sub-Total	:	\$	9,961.80
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	9,961.80
GST 7%	:	\$	697.33
Grand Total	:	\$	10,659.13
Finalise By/Date	:	LOI / 06/10/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000				Cust No/Name	FCV02063/WONG SHAW PING			
				Reg No/Reg Date	SMW6487P / 30/11/2020			
				Date In/Mileage	13/08/2021/ 4595			
				Chassis/Package	VF73AHNSRKJ762009 /#			
				Engine No	10XVAY1500442			
				Make/Model	CIT/GRAND C4 SPACETOURER 1.2 EURO 6.2			
				Colour/Trim	POW POLAR WHITE / 26F TERPA BLEU			
								
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
FAX00001	Credit	08/10/2021/ 11:07	BLK	260 / AiTing	16817	0		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH REAR FENDER, LH REAR DOOR, REPAIR REAR BUMPER, & ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2500.00
E PNT98000 RESPRAY ON REAR BUMPER, LH REAR FENDER, LH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1140.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 80.00
E PNT88000 TRANSFER LH REAR DOOR ATTACHMENTS TO NEW PANEL								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR								✓ 120.00
M SUNDRY APPLY BODT SEALANT ON AFFECTED AREAS								✓ 80.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 50.00
A 10028901 CONDUCT DIAGNOSTIC CHECK AND CLEAR TROUBLE CODE								✓ 225.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
S SPECIALISTJOB SUPPLY LH REAR DOOR QUARTER GLASS SOLAR FILM - RIKECOOL								8 80.00
X	RR QTR MOULDING LH				1.00	✓ 381.00	20.00	304.80
X	REAR WING LH				1.00	✓ 2057.00	20.00	1645.60
X	REAR DOOR LH ASS				1.00	✓ 1556.00	20.00	1244.80

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name FCV02063/WONG SHAW PING Reg No/Reg Date SMW6487P / 30/11/2020 Date In/Mileage 13/08/2021/ 4595 Chassis/Package VF73AHNSRKJ762009 /# Engine No 10XVAY1500442 Make/Model CIT/GRAND C4 SPACETOUREUR 1.2 EURO 6.2 Colour/Trim POW POLAR WHITE / 26F TERPA BLEU

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	08/10/2021/ 11:07	BLK	260 / AiTing	16817	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REAR DOOR SEAL LH INFERIEUR	1.00	✓ 112.00	20.00	89.60
X REAR DOOR SEAL LH	1.00	✓ 239.00	20.00	191.20
X DECOR STRIP LH	1.00	✓ 200.00	20.00	160.00
X DOOR FIXINGS	1.00	✓ 222.00	20.00	177.60
X ALLOY WHEEL 6.5 J16 CH5-47	1.00	✓ 593.00	20.00	474.40
X WINDOW OUTSIDE LH	1.00	102.00	20.00	81.60
X DOOR LOCK LH	1.00	328.00	20.00	262.40
X WINDOW LIFTER LH	1.00	620.00	20.00	496.00
X SIDE WINDOW LH	1.00	286.00	20.00	228.80

Z TEXT
 AIG OD CLAIM.
 DOA : 13.08.21
 SURVEYOR STEVE-LKK 13.08.21
 POLICY NO : 2070160416 REPAIR 10 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,356.80		Nett	9,961.80
Labour	4,355.00	7% GST on	9961.80	697.33
Standard Menu	0.00			
Specialist Job	110.00		Total Payable	10,659.13
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	140.00		Total Due	10,659.13
Total(w/o GST)	9,961.80			

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLW 6487 P

<u>Materials</u>		<u>Cost (\$)</u>
1	Window outside LH	102.00
2	Door Lock LH	328.00
3	Window lifter LH	620.00
4	Side Window LH	286.00
Total		1,336.00
Less 20% discount		267.20
Total after discount		1,068.80
7% GST		74.82
Grand total		<u>\$ 1,143.62</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER-ADMIN
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

Work Order: R001534
 License: SMW 6487 P
 Technician: 106 WENG SOON
 Mileage: 4595
 Date: 24.9.21 18:54

Citroen GC4P 1.2Puretech from 2018

Front : Left

Actual	Before	Specified Range
		-0°33' -0°03'
3°26'	3°26'	3°42' 4°42'
		-0°12' -0°05'
11°07'	11°07'	13°30' 14°30'
11°01'	11°01'	12°57' 14°27'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
		-0°33' -0°03'
		3°42' 4°42'
		-0°12' -0°05'
11°17'	11°17'	13°30' 14°30'
11°04'	11°04'	12°57' 14°27'

Front

	Actual	Before	Specified Range
Cross Camber			-0°20' 0°20'
Cross Caster	-0°34'	-0°34'	-0°20' 0°20'
Cross SAI	-0°10'	-0°10'	
Total Toe			-0°24' -0°09'
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
		-1°57' -1°27'
		0°12' 0°32'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
1°36'	1°36'	-1°57' -1°27'
0°15'	0°15'	0°12' 0°32'

Rear

	Actual	Before	Specified Range
Cross Camber	0°08'	0°08'	-0°30' 0°30'
Total Toe	0°29'	0°29'	0°36' 0°51'
Thrust Angle	-0°01'	0°00'	
Axle Offset	0mm	0mm	

User: DA11572

Vehicle : C4 PICASSO C4 SPACETOURER/C4
SPACETOURER (B78)

VIN: VF73AHNSRKJ762009

Reg No: 81W6481P

Defect to my engine to
Break all the fuel

Print date : Saturday, 25 September 2021 12:58:43

Start of vehicle session : 25/09/2021 - 12:35

Tool version : 09.110




Global test

Expert/Global test

Vehicle/menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT



Built-in systems interface

BSI2010_EV (1 Faults)

B1003 00

Configuration fault (warning, this fault may be a phantom fault)

Properties

Cause

Local

Status

Intermittent


Features

-



Engine management ECU

CMM_VD56




Urea ECU

Communication error




**Anti-lock Braking System (ABS)
or Electronic Stability Program
(ESP)**

ESP90



**Automatic or piloted manual
gearbox**

⚠ ECU not recognised
Down-grade mode: this information is
not guaranteed



Controls under the steering wheel

⚠ ECU not recognised
Down-grade mode: this information is
not guaranteed



**Controls on the steering wheel /
integral controls steering wheel**

VCI



Left-hand windscreen wiper motor *MOTEV_UDS*




Right-hand windscreen wiper motor *MOTED_UDS*



Air conditioning *BCC*



Instrument panel *CIROCCO*



Rain and brightness sensor *PLUIE_LUMINOSITE_UDS*



Airbags and pretensioners ECU *RBG_UDS*



Battery charge status control unit *✱ ECU not recognised*
Down-grade mode: this information is not guaranteed



Multifunction control panel *✱ ECU not recognised*
Down-grade mode: this information is not guaranteed



Parking assistance *AAS_UDS*



Telematic unit (RTx) or audio-navigation *✱ ECU not recognised (1 Faults)*
Down-grade mode: this information is not guaranteed

B1003 55

ECU not recognized : select the "Fault reading" menu to access the description of the fault code

Properties

Status

Permanent

Characterisation of the fault

No configuration



Electronic key reader

Communication error



Signalling fuse box

BSG_S




Driver's door module

PDPC_UDS



Power steering

DAE_BVH2




Motorised Boot Unit

VERINS_MOTORISES



Additional heating

Communication error



Hands full access ECU, right-hand side or rear

BAAST



Touch screen

✱ *EMF_DGT_LVDS_BD*
Important, ECU present on the vehicle but configured absent




Electric steering lock

AVE




Engine wiring housing

Not present




Trailer relay unit

Not present




External CD player

Not present




Audio amplifier

Not present




Multifunction video camera (CMF)

Not present












Anti-theft alarm

Not present



Intrusion alarm siren

Not present

	Vehicle Distance Assistance	Not present
	Seat driver position memory module.	Not present
	Right-hand reversible seat belt inertia reel	Not present
	Left-hand reversible seat belt inertia reel	Not present
	Dynamic headlamp height adjuster	Not present
	Supplies protection and management unit	Not present
	Automatic gearbox electric control ECU	Not present
	Hands-free unit	Not present
	Service module / Independent telematic unit	Not present
	Voltage maintaining device	Not present
	Diesel additive pump	Not present
	Panoramic visual assistance ECU	Not present
	Driver's seat comfort ECU	Not present

Help