

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21008515/GEA3Q2**Date:** 18/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SMZ1261R **Insured Vehicle No :** SLS9831S  
 Date of Loss: 11/08/2021 Nature of Claim: TP Claim No: MFL2021D0003511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ1261R**  
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZR2G88630  
 Reg. Date: 12/04/2021 (Man. Year: 2020) Chassis No: JTDKB3FU503091814  
 Colour: Silver Odometer: 24904 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 13,830.00         | 7,059.25          | 6,770.75          | 48.96         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 5,930.00          | 3,370.00          | 2,560.00          | 43.17         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>19,760.00</b>  | <b>10,429.25</b>  | <b>9,330.75</b>   | <b>47.22</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>8,300.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 19,760.00         | 8,300.00          | 11,460.00         | 58.00         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,383.20          | 581.00            | 802.20            | 58.00         |
| <b>Nett Amount (S\$)</b>                        | <b>21,143.20</b>  | <b>8,881.00</b>   | <b>12,262.20</b>  | <b>58.00</b>  |
| <b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b> |                   | 560.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.49              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>9,448.49</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>9,440.00</b>   |                   |               |

INSPECTION

Date of Assignment: 13/08/2021  
 Date Inspected: 13/08/2021 Inspected At: My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)  
 60 Jalan Lam Huat, Carros Centre #05-21  
 Singapore 737869  
 Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                   |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                   |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 21 Jan 2022)                     |
| Parts:        | 144                                                                                                                                                                          | TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                 |
| Print Code:   | (Unsubmitted, no print-code for SMZ1261R)                                                                                                                                    |                                                                   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                   |

Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *TAILGATE                             | Buckled       | 1,459.00 FL | *1,147.80 FL |
| 2   | 1   |          | *TAILGATE WEATHERSTRIP                | Twisted       | 212.00 FL   | *212.00 FL   |
| 3   | 1   |          | *TAILGATE OUTER GARNISH               | Distorted     | 681.00 FL   | *681.00 FL   |
| 4   | 1   |          | *TAILGATE LOGO                        | Necessary     | 95.50 FL    | *47.90 FL    |
| 5   | 1   |          | *TAILGATE EMBLEM PRIUS                | Necessary     | 89.40 FL    | *54.60 FL    |
| 6   | 1   |          | *TAILGATE EMBLEM HYBRID               | Necessary     | 82.30 FL    | *54.60 FL    |
| 7   | 1   |          | *TAILGATE DETECTOR                    | Damaged       | 321.00 FL   | *72.00 FL    |
| 8   | 1   |          | *TAILGATE LOCK                        | Bent          | 312.00 FL   | *312.00 FL   |
| 9   | 1   |          | *TAILGATE WINDSCREEN MOULDING         | Necessary     | 198.00 FL   | *85.40 FL    |
| 10  | 1   |          | *TAILGATE WIPER MOTOR                 | Not Necessary | 689.00 FL   | *- FL        |
| 11  | 1   |          | *TAILGATE INNER TRIM BOARD            | Broken        | 459.00 FL   | *259.20 FL   |
| 12  | 2   |          | *TAILGATE LAMP                        | Cracked       | 718.00 FL   | *718.00 FL   |
| 13  | 1   |          | *REAR BUMPER                          | Distorted     | 789.00 FL   | *442.60 FL   |
| 14  | 1   |          | *REAR BUMPER SIDE RETAINER            | Not Necessary | 112.00 FL   | *- FL        |
| 15  | 1   |          | *REAR BUMPER REINFORCEMENT            | Bent          | 350.50 FL   | *332.70 FL   |
| 16  | 2   |          | *REAR BUMPER BRACKET                  | Not Necessary | 228.00 FL   | *- FL        |
| 17  | 1   |          | *REAR BUMPER LIP                      | Distorted     | 728.90 FL   | *552.60 FL   |
| 18  | 2   |          | *REAR BUMPER REFLECTOR                | Cracked       | 136.00 FL   | *78.00 FL    |
| 19  | 1   |          | *REAR BUMPER UNDER COVER              | Broken        | 298.00 FL   | *229.90 FL   |
| 20  | 1   |          | *REAR FENDER LH                       | Repair        | 898.00 FL   | *- FL        |
| 21  | 2   |          | *REAR FENDER COWLING                  | Not Necessary | 396.40 FL   | *- FL        |
| 22  | 2   |          | *REAR FENDER INNER TRIM               | Deformed      | 1,218.00 FL | *725.00 FL   |
| 23  | 2   |          | *TAILAMP                              | Broken        | 1,108.00 FL | *1,108.00 FL |
| 24  | 2   |          | *TAILAMP LOWER BRACKET                | Not Necessary | 164.00 FL   | *- FL        |
| 25  | 1   |          | *REAR END PANEL                       | Buckled       | 612.00 FL   | *612.00 FL   |
| 26  | 1   |          | *REAR END PANEL TOP GARNISH           | Broken        | 212.00 FL   | *165.80 FL   |
| 27  | 1   |          | *REAR FLOOR PANEL                     | Repair        | 1,025.00 FL | *- FL        |
| 28  | 1   |          | *REAR FLOOR PANEL TOP BOARD           | Deformed      | 325.00 FL   | *229.90 FL   |
| 29  | 1   |          | *REAR FLOOR PANEL TOP TRAY            | Cracked       | 458.00 FL   | *398.00 FL   |
| 30  | 1   |          | *REAR FLOOR PANEL TOP SPONGE          | Not Necessary | 411.00 FL   | *- FL        |
| 31  | 1   |          | *REAR EXHAUST PIPE                    | Not Necessary | 989.00 FL   | *- FL        |
| 32  | 1   |          | *REAR BUMPER CLIPS                    | Necessary     | 80.00 FS    | *30.00 FS    |
| 33  | 1   |          | *REAR TAILGATE INNER TRIM BOARD CLIPS | Necessary     | 80.00 FS    | *30.00 FS    |
| 34  | 1   |          | *REAR WINDSCREEN SEALANT              | Necessary     | 80.00 FS    | *30.00 FS    |
| 35  | 1   |          | *REAR WINDSCREEN INNER SEAL           | Necessary     | 80.00 FS    | *20.00 FS    |
| 36  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS     | Necessary     | 50.00 FS    | *30.00 FS    |
| 37  | 1   |          | *REAR NUMBER PLATE                    | Cut           | 50.00 FS    | *10.00 FS    |
| 38  | 1   |          | *REAR NUMBER PLATE GARNISH            | Cut           | 50.00 FS    | *20.00 FS    |
| 39  | 1   |          | *REAR REVERSE SENSOR                  | Damaged       | 250.00 FS   | *200.00 FS   |
| 40  | 1   |          | *REAR REVERSE CAMERA                  | Damaged       | 350.00 FS   | *250.00 FS   |
| 41  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS     | Necessary     | 80.00 FS    | *10.00 FS    |
| 42  | 1   |          | *REAR END PANEL SEALANT               | Necessary     | 60.00 FS    | *40.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |           |          |
|-----------------------------------------------------|-----------|----------|
| Sub Total (\$\$)                                    | 16,985.00 | 9,189.00 |
| - List Item Discount on L Items 20.00/25.00% (\$\$) | 3,155.00  | 2,129.75 |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|----------|
| Total Parts (S\$)                             |     |          |             |           | 13,830.00  | 7,059.25 |
| Report was unsubmitted during this print-out. |     |          |             |           |            |          |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                           |          |                 |                 |
| 1                               | TO CHECK REAR ELECTRICAL WIRING           | New      | 150.00          | 30.00           |
| 2                               | RESET TROUBLE CODE                        | New      | 300.00          | 50.00           |
| 3                               | BODY COATING                              | New      | 300.00          | 0.00            |
| 4                               | TOWING                                    | New      | 100.00          | 50.00           |
| 5                               | TO REMOVE AND RENEW REVERSE SENSOR        | New      | 150.00          | 40.00           |
| 6                               | TO REMOVE AND REFIT REAR GLASS            | New      | 150.00          | 120.00          |
| 7                               | REMOVE AND RENEW REAR GARNISH /UPHOLSTERY | New      | 200.00          | 60.00           |
| 8                               | REMOVE AND RENEW TAILGATE MECHANISM       | New      | 80.00           | 60.00           |
| 9                               | REMOVE AND RENEW REAR EXHAUST SILENCER    | New      | 150.00          | 0.00            |
| 10                              | TO RESPRAY UNDERCOATING }                 | New      | 150.00          | 60.00           |
| 11                              | APPLY ANTI RUST ON AFFECTED AREAS }       | New      | 200.00          | 0.00            |
| 12                              | SPRAY PAINTING ON AFFECTED AREAS          | New      | 2,000.00        | 1,600.00        |
| 13                              | PANEL BEATING ON AFFECTED AREAS           | New      | 2,000.00        | 1,300.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>5,930.00</b> | <b>3,370.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >