

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s MY CAR CONSULTANT

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	

Bal. or Market Value: \$121k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMZ1261R

Yr Regn: 12 Apr/2021

Type: ☒ M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS c.c. 1798

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 24904 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU503091814 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/R or

Tyre Size: F: 195/65R15

R: 195/65R15

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 13-08-2021

Survey held at W/S 4PM

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Filed:

Long Cond / MPB:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date: 12/8/2021

Vehicle: SMZ1261R

Make / Model: TOYOTA PRIUS

Chassis:

No.	Description	Unit	Unit Price	Amount	
1	TAILGATE / <i>huc</i>	1	\$ 1,459.00	\$ 1,459.00	1147.8
2	TAILGATE WEATHERSTRIP / <i>huc</i>	1	\$ 212.00	\$ 212.00	✓
3	TAILGATE OUTER GARNISH / <i>CH</i>	1	\$ 681.00	\$ 681.00	✓
4	TAILGATE LOGO / <i>huc</i>	1	\$ 95.50	\$ 95.50	47.9
5	TAILGATE EMBLEM PRIUS / <i>huc</i>	1	\$ 89.40	\$ 89.40	54.6
6	TAILGATE EMBLEM HYBRID / <i>huc</i>	1	\$ 82.30	\$ 82.30	54.6
7	TAILGATE DETECTOR / <i>DM</i>	1	\$ 321.00	\$ 321.00	72
8	TAILGATE LOCK / <i>BT</i>	1	\$ 312.00	\$ 312.00	✓
9	TAILGATE WINDSCREEN MOULDING / <i>huc</i>	1	\$ 198.00	\$ 198.00	85.4
10	TAILGATE WIPER MOTOR / <i>X NN</i>	1	\$ 689.00	\$ 689.00	X
11	TAILGATE INNER TRIM BOARD / <i>huc</i>	1	\$ 459.00	\$ 459.00	259.2
12	TAILGATE LAMP / <i>CPA</i>	2	\$ 359.00	\$ 718.00	✓
13	REAR BUMPER / <i>huc</i>	1	\$ 789.00	\$ 789.00	442.6
14	REAR BUMPER SIDE RETAINER / <i>X NN</i>	1	\$ 112.00	\$ 112.00	X
15	REAR BUMPER REINFORCEMENT / <i>BT</i>	1	\$ 350.50	\$ 350.50	332.7
16	REAR BUMPER BRACKET / <i>X NN</i>	2	\$ 114.00	\$ 228.00	X
17	REAR BUMPER LIP / <i>huc</i>	1	\$ 728.90	\$ 728.90	552.6
18	REAR BUMPER REFLECTOR / <i>huc</i>	2	\$ 68.00	\$ 136.00	78
19	REAR BUMPER UNDER COVER / <i>huc</i>	1	\$ 298.00	\$ 298.00	229.9
20	REAR FENDER LH / <i>Repair X</i>	1	\$ 898.00	\$ 898.00	X
21	REAR FENDER COWLING / <i>X NN</i>	2	\$ 198.20	\$ 396.40	X
22	REAR FENDER INNER TRIM / <i>huc</i>	2	\$ 612.00	\$ 1,218.00	725
23	TAILAMP / <i>huc</i>	2	\$ 554.00	\$ 1,108.00	✓
24	TAILAMP LOWER BRACKET / <i>X NN</i>	2	\$ 82.00	\$ 164.00	X
25	REAR END PANEL / <i>huc</i>	1	\$ 612.00	\$ 612.00	✓
26	REAR END PANEL TOP GARNISH / <i>huc</i>	1	\$ 212.00	\$ 212.00	165.8
27	REAR FLOOR PANEL / <i>X Repair</i>	1	\$ 1,025.00	\$ 1,025.00	X
28	REAR FLOOR PANEL TOP BOARD / <i>huc</i>	1	\$ 325.00	\$ 325.00	229.9
29	REAR FLOOR PANEL TOP TRAY / <i>huc</i>	1	\$ 458.00	\$ 458.00	398
30	REAR FLOOR PANEL TOP SPONGE / <i>X NN</i>	1	\$ 411.00	\$ 411.00	X
31	REAR EXHAUST PIPE / <i>X NN</i>	1	\$ 989.00	\$ 989.00	X
			25	\$ 15,775.00	8519
			Less 20%	\$ 3,155.00	
			Total	\$ 12,620.00	6389.25
S/Nett items:					
1	REAR BUMPER CLIPS / <i>huc</i>	1	\$ 80.00	\$ 80.00	30
2	REAR TAILGATE INNER TRIM BOARD CLIPS / <i>huc</i>	1	\$ 80.00	\$ 80.00	30
3	REAR WINDSCREEN SEALANT / <i>huc</i>	1	\$ 80.00	\$ 80.00	30
4	REAR WINDSCREEN INNER SEAL / <i>huc</i>	1	\$ 80.00	\$ 80.00	30
5	REAR FENDER INNER TRIM CLIPS SET / <i>huc</i>	1	\$ 50.00	\$ 50.00	30

6	REAR NUMBER PLATE / <i>cut</i>	1	\$ 50.00	\$ 50.00	10
7	REAR NUMBER PLATE GARNISH / <i>cut</i>	1	\$ 50.00	\$ 50.00	20
8	REAR REVERSE SENSOR / <i>PM</i>	1	\$ 250.00	\$ 250.00	200
9	REAR REVERSE CAMERA / <i>PM</i>	1	\$ 350.00	\$ 350.00	250
10	REAR END PANEL TOP GARNISH CLIPS / <i>3x6</i>	1	\$ 80.00	\$ 80.00	10
11	REAR END PANEL SEALANT / <i>3x6</i>	1	\$ 60.00	\$ 60.00	40
				\$ 1,210.00	670
	Labour to:FRONT AND REAR				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00	30
2	RESET TROUBLE CODE	1	\$ 300.00	\$ 300.00	50
3	BODY COATING <i>NN</i>	1	\$ 300.00	\$ 300.00	60 X
4	TOWING	1	\$ 100.00	\$ 100.00	50
5	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00	40
6	TO REMOVE AND REFIT REAR GLASS	1	\$ 150.00	\$ 150.00	120
7	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 200.00	\$ 200.00	60
8	REMOVE AND RENEW TAILGATE MECHANISM	1	\$ 80.00	\$ 80.00	60
9	REMOVE AND RENEW REAR EXHAUST SILENCER <i>NN</i>	1	\$ 150.00	\$ 150.00	X
10	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	160
11	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	7
12	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 2,000.00	\$ 2,000.00	2600
15	PANEL BEATING ON AFFECTED AREAS	1	\$ 2,000.00	\$ 2,000.00	1300
				\$ 5,930.00	
					3370
			Parts Replacement Amount	\$ 13,830.00	
			Total Amount for Labour	\$ 5,930.00	
			Total Amount	\$ 19,760.00	

10429.25

-20%: 8300

Gino Qianf
 82880282
 13/8/2021
 Lumpsum repair
 After repair photos.
 10 Days.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: