

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008520/UTCN2**Date:** 24/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004222101		
Claimant Vehicle No :	SLA6472J	Insured Vehicle No :	SLU1430H		
Date of Loss:	23/07/2021	Nature of Claim:	TP	Claim No:	SNM21D204089/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA6472J	Engine No:	L15B4028774
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11108773
Reg. Date:	10/03/2016 (Man. Year: 2015)	Odometer:	74554 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,361.20	1,091.52	1,269.68	53.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	790.00	620.00	43.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,771.20	1,881.52	1,889.68	50.11
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	3,771.20	1,500.00	2,271.20	60.22
+ GST 7.00/7.00% (\$\$)	263.98	105.00	158.98	60.22
Nett Amount (\$\$)	4,035.18	1,605.00	2,430.18	60.22

INSPECTION

Date of Assignment:	13/08/2021		
Date Inspected:	18/08/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA6472J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR FENDER WHEEL ARCH GARNISH	Distorted	255.00 FL	*208.20 FL
2	1		*O/S ROCKER PANEL GARNISH	Not Necessary	536.00 FL	*- FL
3	1		*O/S REAR DOOR	Badly Dented	1,050.00 FL	*986.20 FL
4	1		*O/S REAR DOOR OUTER WEATHERSTRIP MOULDING	Not Necessary	128.00 FL	*- FL
5	1		*O/S REAR DOOR WEATHERSTRIP LOWER	Necessary	85.00 FL	*85.00 FL
6	1		*O/S REAR DOOR WEATHERSTRIP FRONT	Necessary	85.00 FL	*85.00 FL
7	1		*O/S REAR WHEEL RIM	Repair	650.00 FS	*- FS
					Sub Total (\$\$)	2,789.00 1,364.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	427.80 272.88
					Total Parts (\$\$)	2,361.20 1,091.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TYRE,RIM AND ON WHEEL BALANCING	New	50.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
3	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	100.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
5	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	250.00	250.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	400.00
Gross Labour Cost (\$\$)			1,410.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >