

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21008522/ETCE2

Date: 02/09/2021

REFERENCE

Insured/Claimant: NGO KENG SIEN Policy No: DMPCSNW00155022000
Date of Loss: 25/05/2021 Nature of Claim: OD Claim No: SNM21D204459/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF3744G**
Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11031448
Reg. Date: 07/11/2018 (Man. Year: 2018) Chassis No: JHMGK3850JX227201
Colour: White Odometer: 37531 km
Engine Capacity: 1318 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,346.03	2,084.06	4,261.97	67.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,590.00	3,660.00	4,930.00	57.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,936.03	5,744.06	9,191.97	61.54
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,436.03	5,244.06	9,191.97	63.67
+ GST 7.00/7.00% (S\$)	1,010.52	367.08	643.44	63.67
Nett Amount (S\$)	15,446.55	5,611.14	9,835.41	63.67

INSPECTION

Date of Assignment: 13/08/2021

Date Inspected: 16/08/2021 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore 159937

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2021)
Parts:	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3744G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING - L (N)	Not Necessary	45.00 FS	*- FS
2	1		*HEADLIGHT ASSY,R.	Not Necessary	485.92 FS	*- FS
3	1		*HEADLIGHT ASSY,L.	Cut	485.92 FS	*485.92 FS
4	1		*HOOD COMP	Dented	544.54 FS	*544.54 FS
5	1		*COVERFR GRILLE	Not Necessary	12.25 FS	*- FS
6	1		*GRILLE ASSYFR.	Not Necessary	261.44 FS	*- FS
7	1		*CLIP.BUMPER (4PCS)	Necessary	8.74 FS	*8.74 FS
8	1		*FACE,FR.BUMPER	Dented	511.19 FS	*511.19 FS
9	1		*LOWER GRILLE,FR.BUMPER	Not Necessary	30.68 FS	*- FS
10	1		*GARNISHR.FR.BUMPER	Not Necessary	12.25 FS	*- FS
11	1		*COVERFR.TOWING	Not Necessary	14.63 FS	*- FS
12	1		*GARNISHL.FR.BUMPER	Not Necessary	12.25 FS	*- FS
13	1		*SPOILERFR.BUMPER LIP	Not Necessary	62.89 FS	*- FS
14	1		*BEAM COMPFR.BUMPER	Not Necessary	226.76 FS	*- FS
15	1		*BRACKETR.HEADLIGHT	Not Necessary	24.41 FS	*- FS
16	1		*BASEFR LICENCE PLATE	Not Necessary	52.72 FS	*- FS
17	1		*BRACKETL.HEADLIGHT	Not Necessary	20.80 FS	*- FS
18	1		*SPACERR.FR BUMPER	Necessary	9.88 FS	*9.88 FS
19	1		*SPACERL.FR BUMPER	Necessary	9.88 FS	*9.88 FS
20	1		*CLIP.BUMPER (17PCS)	Necessary	37.14 FS	*37.14 FS
21	1		*PANEL,R.FR.FENDER	Not Necessary	403.84 FS	*- FS
22	1		*PANEL,L.FR.FENDER	Dented	403.84 FS	*403.84 FS
23	1		*FENDER ASSYR.FR INNER	Not Necessary	74.19 FS	*- FS
24	1		*CLIP ABUMPER (6PCS)	Necessary (3Pcs Only)	14.82 FS	*7.41 FS
25	1		*CLIP,INNER FENDER (22PCS)	Necessary (11Pcs Only)	58.52 FS	*29.26 FS
26	1		*BULKHEAD COMPFR.	Not Necessary	386.74 FS	*- FS
27	1		*CONDENSER ASSY	Not Necessary	669.18 FS	*- FS
28	1		*RADIATOR COMP	Not Necessary	1,227.11 FS	*- FS
29	6		*COOLANT ANTI-FREEZE TYPE 2	Not Necessary	132.24 FS	*- FS
30	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
31	1		*LABEL AIR CON	Necessary	0.85 FS	*0.85 FS
32	1		*LABELCOOLANT INFORMATION	Necessary	5.41 FS	*5.41 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **6,346.03** **2,084.06**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISM & FOCUS	New	180.00	150.00
2	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	480.00	0.00
3	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	430.00	0.00
4	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	New	4,000.00	1,950.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	New	3,500.00	1,560.00
Gross Labour Cost (\$\$)			8,590.00	3,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >