

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21008523/UPA3Q2

Date:

07/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D18MPC0001355_02

Claimant Vehicle No : SMC2529J**Insured Vehicle No :**

SJJ1741S

Date of Loss: 09/08/2021

Nature of Claim:

TP

Claim No:

MPC2021D0003458

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMC2529J**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT (A)

Engine No:

HRA2640763A

Reg. Date: 28/06/2018 (Man. Year: 2018)

Chassis No:

SJNFEAJ11U2311936

Colour: Grey

Odometer:

27913 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Bridgestone 7 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,956.56	887.36	1,069.20	54.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,198.00	1,243.00	955.00	43.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,154.56	2,130.36	2,024.20	48.72
+ GST 7.00/7.00% (S\$)	290.82	149.13	141.69	48.72

Nett Amount (S\$)	4,445.38	2,279.49	2,165.89	48.72
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
(S\$)		2,459.49		
Liabe Amount (80.00%) (S\$)		1,967.59		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,975.04		
Global Sum Settlement (S\$)		1,980.00		

INSPECTION

Date of Assignment: 17/08/2021

Date Inspected: 17/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Autolution Industrial Pte Ltd (HQ)
19 UBI ROAD 4
Singapore 408623

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC2529J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE BRACKET RR BUMPER	Not Necessary	38.90 FN	*- FN
2	1		*LH SIDE BRACKET RR BUMPER	Not Necessary	38.90 FN	*- FN
3	1		*RH STAY RR BUMPER	Not Necessary	141.00 FN	*- FN
4	1		*LH STAY RR BUMPER	Not Necessary	141.00 FN	*- FN
5	1		*REINFORCEMENT RR BUMPER	Repair	691.50 FN	*- FN
6	1		*ENERGY ABSORBER RR BUMPER	Not Necessary	141.40 FN	*- FN
7	1		*TOW HOOK COVER RR BUMPER	Not Necessary	18.80 FN	*- FN
8	1		*REAR BUMPER	Deformed	796.70 FN	*796.70 FN
9	4		*EYE REVERSE SENSOR	Shorted	250.00 FS	*250.00 FS
10	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,358.20	1,046.70
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	401.64	159.34
Total Parts (\$\$)	1,956.56	887.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR RR END PANEL RENEW REAR BUMPER	New	1,170.00	585.00
2	CHARGES TO SPRAY PAINTING REAR END PANEL AND REAR BUMPER	New	750.00	500.00
3	RENEW REVERSE SENSOR	New	110.00	110.00
4	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	New	48.00	48.00
5	COMPUTER CHECK DIAGNOSIS	New	120.00	0.00
Gross Labour Cost (S\$)			2,198.00	1,243.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >