

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURANCE BHD		Ref:	CS3/LPC21008526/R1qf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date	9: 20/08/2021	
			Cod	e: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBD 8184E	Veh. Inspected	GBE 6506T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	21/21/21/VC05/024843	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	13/08/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE 3.0DX M	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KDH2010184423	Colour	GREY	
	Odometer	205152 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	DUNLOP	6 mm	
	L/H Front Tyre	195 R15C	DUNLOP	6 mm	
	R/H Rear Tyre	195 R15C	DUNLOP	6 mm	
	L/H Rear Tyre	195 R15C	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE FRO			
5.	General Information				
	Accident Date	11/08/2021	Inspect Date / Time	16/08/2021 (10:32 AM)	
	Survey held at	WILLY MOTOR COMPANY			
		27A JURONG PORT ROAD #01-32 SINGAPORE 619101			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21008526/R1qf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser