



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 6910B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	AIR CLEANER RESONATOR BOX	SERVICEABLE	358.10	-
1	FRONT BUMPER	REPLACED	459.75	459.75
1	FRONT BUMPER LH FOGLAMP	NOT NECESSARY	210.80	-
1	FRONT BUMPER LH FOGLAMP COVER	NOT NECESSARY	132.10	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	177.25	-
2	FRONT BUMPER SIDE RETAINER L/R	SERVICEABLE	132.00	-
1	FRONT BUMPER UPPER RUBBER SEAL	NOT NECESSARY	85.30	-
1	FRONT LH ABS SENSOR	NOT NECESSARY	237.40	-
1	FRONT LH FENDER	REPAIRED SEE LABOUR	290.50	-
1	FRONT LH FENDER 'VVT-I' EMBLEM	REPLACED	69.88	69.88
1	FRONT LH HEADLAMP	REPLACED	398.70	398.70
1	FRONT LH HEADLAMP LOWER BRACKET	NOT NECESSARY	35.10	-
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	435.00	-
1	FRONT LH KNUCKLE ARM BEARING	NOT NECESSARY	210.00	-
1	FRONT LH LINKAGE	NOT NECESSARY	115.00	-
1	FRONT LH LOWER ARM	NOT NECESSARY	465.00	-
1	FRONT LH LOWER BALL JOINT	NOT NECESSARY	181.40	-
1	FRONT LH SHOCK ABSORNER	NOT NECESSARY	372.40	-
1	FRONT LH SHOCK ABSORBER RUBBER	NOT NECESSARY	95.10	-
1	FRONT LH SHOCK ABSORBER SPONGE	NOT NECESSARY	115.00	-
1	FRONT LH SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	201.10	-
1	FRONT LH STEERING TIE ROD END	NOT NECESSARY	185.30	-
1	FRONT LH WHEEL HUB	NOT NECESSARY	245.10	-
	LESS 25% DISCOUNT		-1,301.82	-232.08
			3,905.46	696.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	REPLACED	50.00	30.00
1	FRONT LH 15" SPORT RIM (SN)	REPLACED	600.00	350.00
1	FRONT LH 195/65/15 TYRE (SN)	NOT NECESSARY	400.00	-

Report Ref No. CS/LAW21008535/Dvf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
			1,100.00	380.00
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.	NOT NECESSARY	100.00	-
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		180.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		700.00	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER.		600.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	30.00
			1,740.00	920.00
<b>GRAND TOTAL</b>			<b>6,745.46</b>	<b>1,996.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CS/LAW21008535/Dvf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.