



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW21008535/Dvf3e2	
			Date: 13/10/2021	
			Code: L041	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SJZ 6549P	Veh. Inspected	SJQ 6910B
	Policy No.		Coverage (\$)	0.00
	Claim No.	2020001741.NTUC	Excess (\$)	0.00
	Assign From	TEO YI XUAN	Assign Date	13/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053ZEE106144899	Colour	SILVER
	Odometer	207647 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	5 mm
	L/H Front Tyre	195/65 R15	FALKEN	5 mm
	R/H Rear Tyre	195/65 R15	FALKEN	5 mm
	L/H Rear Tyre	195/65 R15	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	26/04/2018	Inspection Date	11/09/2021
	Survey held at	OPEN CARPARK OF 817C Keat Hong Link		
	Repairer	TWINCAR AUTOMOTIVE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	