



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
VISION LAW LLC*			Ref:	CS/LAW21008535/Dvf3e2
133 NEW BRIDGE ROAD #18-01/02 CHINATOWN POINT SINGAPORE 059413			Date:	13/10/2021
			Code:	L029
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	SJZ 6549P	Veh. Inspected	SJQ 6910B
	Policy No.		Coverage (\$)	0.00
	Claim No.	T140.108567.18	Excess (\$)	0.00
	Assign From	TEO YI XUAN	Assign Date	13/08/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053ZEE106144899	Colour	SILVER
	Odometer	207647 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	5 mm
	L/H Front Tyre	195/65 R15	FALKEN	5 mm
	R/H Rear Tyre	195/65 R15	FALKEN	5 mm
	L/H Rear Tyre	195/65 R15	FALKEN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/04/2018	Inspection Date	11/09/2021
	Survey held at	OPEN CARPARK OF 817C Keat Hong Link		
	Repairer	TWINCAR AUTOMOTIVE PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	