

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008538/AVCN2**Date:** 01/11/2021REFERENCE

Insured/Claimant:	KHOO JUNWEI	Policy No:	7210058622		
Date of Loss:	10/08/2021	Nature of Claim:	OD	Claim No:	0602957388SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB948P		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DKY015289
Reg. Date:	10/06/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF25MN053762
Colour:	Green	Odometer:	2818 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$225,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,557.00	11,232.88	7,324.12	39.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,944.00	3,852.00	4,092.00	51.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,501.00	15,084.88	11,416.12	43.08
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	25,701.00	14,284.88	11,416.12	44.42
+ GST 7.00/7.00% (S\$)	1,799.07	999.94	799.13	44.42
Nett Amount (S\$)	27,500.07	15,284.82	12,215.25	44.42

INSPECTION

Date of Assignment:	16/08/2021		
Date Inspected:	13/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	650.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-CENTER	Not Necessary	222.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER-LH	Cracked	39.00 FS	*31.20 FS
5	1		*FRONT BUMPER REINFORCEMENT COVER-LH	Not Necessary	111.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LOWER	Not Necessary	210.00 FS	*- FS
7	1		*FRONT AIR GUIDE GRILLE-LH	Cut	434.00 FS	*346.80 FS
8	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	50.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	226.00 FS	*180.40 FS
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,012.00 FS	*- FS
11	6		*POP RIVET	Not Necessary	5.00 FS	*- FS
12	1		*FRONT BUMPER SUPPORT	Not Necessary	59.00 FS	*- FS
13	1		*FRONT BUMPER BRACKET-LH	Bent	54.00 FS	*43.20 FS
14	1		*FRONT BUMPER GUIDE SECTION-LH	Cracked	44.00 FS	*35.12 FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
16	1		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			NPA			
17	4		*FRONT PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
18	1		*HORN-LOW TONE	Not Necessary	216.00 FS	*- FS
19	1		*HORN BRACKET	Not Necessary	47.00 FS	*- FS
20	1		*FRONT FENDER-LH	Buckled	1,468.00 FS	*1,174.40 FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
22	1		*FRONT FENDER BRACE-LH	Not Necessary	118.00 FS	*- FS
23	1		*FRONT FENDER BRACKET-LH UPPER	Not Necessary	44.00 FS	*- FS
24	1		*FRONT HEADLIGHT MOUNTING-LH	Not Necessary	118.00 FS	*- FS
25	1		*FRONT HEADLIGHT-LH	Cracked	8,624.00 FS	*6,899.20 FS
26	1		*FRONT HEADLIGHT LIFT CYLINDER-LH	Cracked	198.00 FS	*158.40 FS
27	1		*FRONT HEADLIGHT BRACKET-LH	Not Necessary	6.00 FS	*- FS
28	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	182.00 FS	*- FS
29	1		*FRONT FENDER TOP COVER-LH	Not Necessary	36.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	275.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	71.00 FS	*- FS
32	1		*FRONT WHEEL SPOILER-LH	Not Necessary	166.00 FS	*- FS
33	1		*FRONT WHEEL STONE GUARD-LH	Not Necessary	51.00 FS	*- FS
34	1		*FRONT WINDOW CHROME TRIM STRIP-LH OUTER	Not Necessary	200.00 FS	*- FS
35	1		*FRONT WINDOW CHROME TRIM STRIP GUIDE-LH	Not Necessary	257.00 FS	*- FS
36	1		*SUNDRIES	Necessary	350.00 FS	*98.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **18,557.00** **11,232.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRI.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS FRONT DOOR	New	4,000.00	1,650.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (S\$)			7,944.00	3,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >