

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008539/BTF3E2

Date: 13/10/2021

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|----------------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/VMT/21-424912-CA |
| Claimant Vehicle No : | SLB9233H | Insured Vehicle No : | FBA7103L |
| Date of Loss: | 13/08/2021 | Nature of Claim: | TP |
| | | Claim No: | MSC/V/21-000368 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SLB9233H | Engine No: | G4FGGH612119 |
| Make & Model: | KIA FORTE K3, 1.6 EX (A) | Chassis No: | KNAFX411MG5596211 |
| Reg. Date: | 27/04/2016 (Man. Year: 2016) | Odometer: | 129775 km |
| Colour: | Grey | | |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Toyo 5 mm | Rear Left Side: | Toyo 5 mm |
| Front Right Side: | Toyo 5 mm | Rear Right Side: | Toyo 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 8,916.00 | 4,364.27 | 4,551.73 | 51.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,530.00 | 2,320.00 | 2,210.00 | 48.79 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 13,446.00 | 6,684.27 | 6,761.73 | 50.29 |
| Approved Total (Overridden) (S\$) | | 4,750.00 | | |
| (S\$) | 13,446.00 | 4,750.00 | 8,696.00 | 64.67 |
| + GST 7.00/7.00% (S\$) | 941.22 | 332.50 | 608.72 | 64.67 |
| Nett Amount (S\$) | 14,387.22 | 5,082.50 | 9,304.72 | 64.67 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 16/08/2021 | |
| Date Inspected: | 16/08/2021 Inspected At: | Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 13 Oct 2021) |
| Parts: | 143 | KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLB9233H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Broken | 688.00 FL | *688.00 FL |
| 2 | 1 | | *REAR BUMPER RH SIDE RETAINER | Necessary | 32.00 FL | *32.00 FL |
| 3 | 1 | | *REAR BUMPER LOWER SPOILER | Not Damaged | 347.00 FL | *- FL |
| 4 | 1 | | *REAR WINDSCREEN GLASS RUBBER SEAL | Necessary | 37.00 FL | *37.00 FL |
| 5 | 1 | | *RH REAR FENDER | Dented | 1,100.00 FL | *1,100.00 FL |
| 6 | 1 | | *RH REAR FENDER SPLASH SHIELD | Not Damaged | 113.00 FL | *- FL |
| 7 | 1 | | *RH TAILLAMP ASSY | Cut | 772.00 FL | *418.20 FL |
| 8 | 1 | | *RH REAR DOOR | Dented | 1,225.00 FL | *1,225.00 FL |
| 9 | 1 | | *RH REAR DOOR FRAME BLACK TAPE (NO.1) | Necessary | 14.77 FL | *14.77 FL |
| 10 | 1 | | *RH REAR DOOR FRAME BLACK TAPE (NO.2) | Necessary | 14.77 FL | *14.77 FL |
| 11 | 1 | | *RH REAR DOOR OUTER MOULDING | Not Damaged | 109.54 FL | *- FL |
| 12 | 1 | | *RH REAR DOOR GLASS | Not Damaged | 374.70 FL | *- FL |
| 13 | 1 | | *RH REAR SHOCK ABSORBER | Not Damaged | 385.00 FL | *- FL |
| 14 | 1 | | *RH REAR WHEEL BEARING | Not Damaged | 330.00 FL | *- FL |
| 15 | 1 | | *REAR AXLE BEAM | Not Damaged | 2,200.00 FL | *- FL |
| 16 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 70.00 FS | *30.00 FS |
| 17 | 1 | | *RH REAR SPORT RIM | Cut | 800.00 FS | *380.00 FS |
| 18 | 1 | | *RH REAR TYRE | Cut | 320.00 FS | *200.00 FS |
| 19 | 1 | | *BRAKE FLUID | Not Necessary | 50.00 FS | *- FS |
| 20 | 1 | | *REAR WINDSCREEN GLASS SEALANT | Necessary | 70.00 FS | *30.00 FS |
| 21 | 1 | | *REAR WINDSCREEN GLASS INNER SEAL | No such part | 50.00 FS | *- FS |
| 22 | 1 | | *RH ROCKER PANEL | Dented | 575.00 FL | *575.00 FL |
| 23 | 1 | | *RH ROCKER PANEL JOINT SEALANT | Necessary | 70.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 9,747.78 | 4,774.74 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 831.78 | 410.47 |
| Total Parts (S\$) | 8,916.00 | 4,364.27 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS | New | 1,000.00 | 800.00 |
| 2 | SPRAY PAINTING ON AFFECTED PANELS | New | 900.00 | 700.00 |
| 3 | CHECK ALL WIRING AND ALL LIGHTING SYSTEM | New | 80.00 | 0.00 |
| 4 | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS | New | 80.00 | 0.00 |
| 5 | REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR | New | 200.00 | 120.00 |
| 6 | REMOVE AND REINSTALL REAR INNER TRIMS, BOARDS, GARNISH, SEATS AND ROOF LINING TO ASSIST REPAIR | New | 350.00 | 0.00 |
| 7 | REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR | New | 70.00 | 60.00 |
| 8 | REMOVE AND REINSTALL RH REAR DOOR INNER COMPONENTS TO NEW DOOR | New | 100.00 | 80.00 |
| 9 | CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM | New | 100.00 | 60.00 |
| 10 | REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR | New | 450.00 | 0.00 |
| 11 | CUT / WELD RH ROCKER PANEL AND PANEL BEATING AFFECTED AREAS | New | 500.00 | 300.00 |
| 12 | SPRAY PAINTING | New | 500.00 | 200.00 |
| 13 | REMOVE AND REINSTALL RH SIDE INNER TRIMS, SEATS AND ALL ATTACHMENT TO ASSIST REPAIR | New | 200.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 4,530.00 | 2,320.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >