

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC21008543/Gtf3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date:	23/08/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GX 4716H	Veh. Inspected	l	SLA 9752G	
	Policy No.	Z/21/VC00/110454	Coverage (\$)		0.00	
	Claim No.	21/21/21/VC00/024848	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		16/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA ESTIMA AERAS 2.4	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	ACR500091863	Colour		BLACK	
	Odometer	139392 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	HABILEAD		6 mm	
	L/H Front Tyre	215/55 R17	HABILEAD		6 mm	
	R/H Rear Tyre	215/55 R17	HABILEAD		6 mm	
	L/H Rear Tyre	215/55 R17	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	12/08/2021	Inspect Date /	Time	16/08/2021 (05:00 PM)	
	Survey held at	14 amk st 63 blk B				
	Repairer	ASSURE AUTO ASSIST PTE LTD				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21008543/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser