



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7507H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	DEFORMED	350.00	340.00
1	REAR BUMPER REINFORCEMENT (WCP)	BENT	180.00	180.00
1	REAR BUMPER TOW COVER LH (WCP)	MISSING	15.00	15.00
10	REAR BUMPER CLIP @\$2.00 (WCP)	NECESSARY	20.00	20.00
	COST PLUS 10%		56.50	55.50
			621.50	610.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
			300.00	200.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	30.00	-
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		300.00	200.00
	SPRAYPAINTING CHARGES.		300.00	200.00
			630.00	400.00
	GRAND TOTAL		1,551.50	1,210.50
	RECOMMENDED COST OF REPAIRS			1,210.50
	LESS EXCESS			-750.00
	NETT LIABILITY			460.50

Report Ref No. CS/UOI21008547/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.