



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref:	CC4/ASM18013841/Gea3q2-1
8 SHENTON WAY #24-01			Date:	06/10/2021
AXA TOWERSINGAPORE 068811			Code:	ASM
ATTN:VALE OH				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 6865D	Veh. Inspected	SLU 4345B	
Policy No.	GA128694	Coverage (\$)	0.00	
Claim No.	S8M00Q8O	Excess (\$)	0.00	
Assign From		Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA 1.4	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVWZZZ16ZDM001168	Colour	BEIGE	
Odometer	103056 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/07/2018	Inspection Date	16/08/2018	
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	