

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI21008551/Vqf3e2	
	36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877			Date:	13/09/2021	
				Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBG 4475B	Veh. Inspected	l	SDP 297D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21002309MFCV	Excess (\$)		0.00	
	Assign From	ESTHER	Assign Date		16/08/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	AUDI A5 COUPE	c.c		1984	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	WAUZZZ8T4CA049035	Colour		WHITE	
	Odometer	197303 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	255/35Z R19	CONTINENTAL		6 mm	
	L/H Front Tyre	255/35Z R19	CONTINENTAL		6 mm	
	R/H Rear Tyre	255/35Z R19	CONTINENTAL		6 mm	
	L/H Rear Tyre	255/35Z R19	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information					
	Accident Date	05/08/2021	Inspect Date /	Time	03/09/2021 (12:52 PM)	
	Survey held at	No.8 Kaki Bukit ave 4 @ premier #02-13				
	Repairer	AUTO MEGA MALL PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$63,000.00					

Report Ref No. CS3/FCI21008551/Vqf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser