

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21008553/EVF3E2

**Date:** 03/11/2021

### REFERENCE

Insured/Claimant: SELOTERIO EUAN IZMAL BIN LLYAS

Policy No: 2070163588

Date of Loss: 14/08/2021

Nature of Claim: OD

Claim No: 5017808252SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP1900U**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11CQ8571

Reg. Date: 24/11/2020 (Man. Year: 2020)

Chassis No: GF7W0700817

Colour: Blue

Odometer: 7062 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$110,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Toyo 4 mm

Rear Left Side: Toyo 4 mm

Front Right Side: Toyo 4 mm

Rear Right Side: Toyo 4 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------|------------------|------------------|------------------|--------------|
| Parts                         | 17,768.30        | 12,852.69        | 4,915.61         | 27.67        |
| Miscellaneous Items           | 0.00             | 0.00             | 0.00             |              |
| Labour                        | 13,780.00        | 6,795.00         | 6,985.00         | 50.69        |
| Paintwork Labour              | 0.00             | 0.00             | 0.00             |              |
| Towing                        | 0.00             | 0.00             | 0.00             |              |
| <b>Gross Total (S\$)</b>      | <b>31,548.30</b> | <b>19,647.69</b> | <b>11,900.61</b> | <b>37.72</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>2,208.38</b>  | <b>1,375.34</b>  | <b>833.04</b>    | <b>37.72</b> |
| <b>Nett Amount (S\$)</b>      | <b>33,756.68</b> | <b>21,023.03</b> | <b>12,733.65</b> | <b>37.72</b> |

### INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 16/08/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)

209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 12.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *WINDSCREEN GLASS CAMERA        | Missing       | 780.00 FS   | *780.00 FS   |
| 2   | 1   |          | *REVERSE SENSOR                 | Damaged       | 220.00 FS   | *220.00 FS   |
| 3   | 1   |          | *SUNDRIES                       | Necessary     | 30.00 FS    | *30.00 FS    |
| 4   | 1   |          | *FACE, RR BUMPER                | Dented        | 1,018.00 FL | *811.00 FL   |
| 5   | 1   |          | *EXTENSION, RR BUMPER           | Crushed       | 360.00 FL   | *360.00 FL   |
| 6   | 1   |          | *REINFORCEMENT, RR BUMPER, LH   | Not Necessary | 79.00 FL    | *- FL        |
| 7   | 1   |          | *REINFORCEMENT, RR BUMPER, RH   | Bent          | 79.00 FL    | *79.00 FL    |
| 8   | 8   |          | *CLIP, ENG ROOM COVER           | Not Necessary | 16.00 FL    | *- FL        |
| 9   | 1   |          | *PANEL ASSY, TAILGATE           | Dented        | 989.00 FL   | *989.00 FL   |
| 10  | 1   |          | *GARNISH, TAILGATE              | Broken        | 496.00 FL   | *496.00 FL   |
| 11  | 1   |          | *W/STRIP, TAILGATE OPENING      | Not Necessary | 213.00 FL   | *- FL        |
| 12  | 2   |          | *HINGE, TAILGATE                | Bent          | 92.00 FL    | *92.00 FL    |
| 13  | 1   |          | *GAS SPRING, TAILGATE, LH       | Not Necessary | 194.00 FL   | *- FL        |
| 14  | 1   |          | *GAS SPRING, TAILGATE, RH       | Not Necessary | 194.00 FL   | *- FL        |
| 15  | 1   |          | *SENSOR, TAILGATE LOCK, LH      | Not Necessary | 426.00 FL   | *- FL        |
| 16  | 1   |          | *SENSOR, TAILGATE LOCK, RH      | Not Necessary | 426.00 FL   | *- FL        |
| 17  | 1   |          | *MOTOR, POWER TAILGATE          | Not Necessary | 1,986.00 FL | *- FL        |
| 18  | 1   |          | *LATCH, TAILGATE                | Bent          | 477.00 FL   | *477.00 FL   |
| 19  | 1   |          | *STRIKER, TAILGATE LATCH        | Bent          | 19.00 FL    | *19.00 FL    |
| 20  | 1   |          | *GLASS, TAILGATE WINDOW         | Broken        | 657.00 FL   | *657.00 FL   |
| 21  | 2   |          | *DAM, TAILGATE SIDE             | Necessary     | 54.00 FL    | *54.00 FL    |
| 22  | 4   |          | *FASTENER, WINDSHIELD           | Necessary     | 24.00 FL    | *24.00 FL    |
| 23  | 1   |          | *DAM, TAILGATE, UPR             | Necessary     | 13.00 FL    | *13.00 FL    |
| 24  | 2   |          | *STOPPER, WINDSHIELD GLASS      | Necessary     | 6.00 FL     | *6.00 FL     |
| 25  | 1   |          | *DAM, TAILGATE, LWR             | Necessary     | 41.00 FL    | *41.00 FL    |
| 26  | 1   |          | *MARK, OUTLANDER                | Necessary     | 95.00 FL    | *95.00 FL    |
| 27  | 1   |          | *PANEL, RR END                  | Dented        | 326.00 FL   | *326.00 FL   |
| 28  | 1   |          | *PANEL, RR END, INR LH<br>(NPA) | Not Necessary | 0.00 FL     | *- FL        |
| 29  | 1   |          | *PANEL, RR END, INR RH          | Not Necessary | 146.00 FL   | *- FL        |
| 30  | 1   |          | *TRIM, RR END                   | Crushed       | 113.00 FL   | *113.00 FL   |
| 31  | 1   |          | *ANT, KEYLESS OPERATION, RR     | Not Necessary | 96.00 FL    | *- FL        |
| 32  | 1   |          | *BUZZER, KEYLESS OPERATIO, RR   | Broken        | 91.00 FL    | *91.00 FL    |
| 33  | 1   |          | *DUCT, RR VENTILATOR            | Not Necessary | 44.00 FL    | *- FL        |
| 34  | 1   |          | *PANEL, QTR, OTR RH             | Dented        | 1,131.00 FL | *1,131.00 FL |
| 35  | 1   |          | *EXTN, QTR PANEL, RR LWR RH     | Dented        | 78.00 FL    | *78.00 FL    |
| 36  | 1   |          | *EXTENSION, QTR PANEL, OTR RH   | Dented        | 276.00 FL   | *276.00 FL   |
| 37  | 1   |          | *GLASS, QTR WINDOW, RH          | Necessary     | 818.00 FL   | *818.00 FL   |
| 38  | 1   |          | *FLOOR, RR                      | Repair        | 751.00 FL   | *- FL        |
| 39  | 1   |          | *LAMP ASSY, COMB, RR LH         | Not Necessary | 603.00 FL   | *- FL        |
| 40  | 1   |          | *LAMP ASSY, COMB, RR RH         | Broken        | 603.00 FL   | *603.00 FL   |
| 41  | 1   |          | *LAMP ASSY, TAIL, LH            | Broken        | 506.00 FL   | *506.00 FL   |
| 42  | 1   |          | *LAMP ASSY, TAIL, RH            | Broken        | 506.00 FL   | *506.00 FL   |
| 43  | 1   |          | *REFLECTOR, TAIL LAMP, LH       | Not Necessary | 100.00 FL   | *- FL        |
| 44  | 1   |          | *REFLECTOR, TAIL LAMP, RH       | Not Necessary | 100.00 FL   | *- FL        |
| 45  | 2   |          | *LAMP ASSY, LICENSE PLATE       | Not Necessary | 68.00 FL    | *- FL        |
| 46  | 1   |          | *MOULDING, RR WHEEL ARCH, LH    | Not Necessary | 168.00 FL   | *- FL        |
| 47  | 1   |          | *MOULDING, RR WHEEL ARCH, RH    | Necessary     | 168.00 FL   | *168.00 FL   |
| 48  | 1   |          | *MOULDING, RR BUMPER, LH        | Necessary     | 88.00 FL    | *88.00 FL    |
| 49  | 1   |          | *MOULDING, RR BUMPER, RH        | Necessary     | 88.00 FL    | *88.00 FL    |
| 50  | 1   |          | *TRIM, TAILGATE                 | Broken        | 329.00 FL   | *329.00 FL   |
| 51  | 1   |          | *BODY KIT, OUTLANDER            | Broken        | 1,554.00 FS | *1,554.00 FS |
| 52  | 1   |          | *REAR SPOILER, COSMIC BLUE      | Not Necessary | 511.00 FN   | *- F         |
| 53  | 1   |          | *DECAL, MIVEC                   | Not Necessary | 36.00 FL    | *- FL        |
| 54  | 1   |          | *BOX, CARGO FLOOR               | Crushed       | 204.00 FL   | *204.00 FL   |
| 55  | 1   |          | *BRKT, R/BMPR FACE SIDE, LH     | Broken        | 12.00 FL    | *12.00 FL    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                        | Condition | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------------------|-----------|-------------|--------------|
| 56  | 1   |          | <b>*BRKT, R/BMPR FACE SIDE, RH</b>                 | Broken    | 12.00 FL    | *12.00 FL    |
| 57  | 1   |          | <b>*EMBLEM MIVEC TECHNOLOGY</b><br>(Supplementary) | Necessary | 30.00 FS    | *30.00 FS    |
| 58  | 1   |          | <b>*HARNESS, RR BUMPER</b><br>(Supplementary)      | Torn      | 84.00 FL    | *84.00 FL    |
| 59  | 13  |          | <b>*CLIPS</b><br>(Supplementary)                   | Necessary | 78.00 FL    | *78.00 FL    |
| 60  | 1   |          | <b>*CAMERA, RR VIEW</b><br>(Supplementary)         | Broken    | 568.00 FL   | *568.00 FL   |
| 61  | 1   |          | <b>*REINF, GATE PILLAR, RH</b><br>(Supplementary)  | Dented    | 250.00 FL   | *250.00 FL   |
| 62  | 3   |          | <b>*GROMMET, TAIL LAMP</b><br>(Supplementary)      | Necessary | 9.00 FL     | *9.00 FL     |
| 63  | 3   |          | <b>*GROMMET, TAIL LAMP</b><br>(Supplementary)      | Necessary | 9.00 FL     | *9.00 FL     |
| 64  | 1   |          | <b>*MUFFLER, EXHAUST MAIN</b><br>(Supplementary)   | Bent      | 582.00 FL   | *582.00 FL   |
| 65  | 1   |          | <b>*PIPE, EXHAUST, CTR</b><br>(Supplementary)      | Bent      | 1,832.00 FL | *1,832.00 FL |
| 66  | 2   |          | <b>*SILENCER, FLOOR</b><br>(Supplementary)         | Necessary | 28.00 FL    | *28.00 FL    |
| 67  | 1   |          | <b>*LID, CARGO FLOOR BOX</b>                       | Crushed   | 295.00 FL   | *295.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>22,275.00</b> | <b>15,911.00</b> |
| <b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b> | 4,404.50         | 3,058.31         |
| <b>- Nett Item Discount on N Items 20.00/0.00% (\$\$)</b>  | 102.20           | 0.00             |
| <b>Total Parts (\$\$)</b>                                  | <b>17,768.30</b> | <b>12,852.69</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                              | Lab.Type | Repairer's       | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                          |          |                  |                 |
| 1                               | RENEW RR BUMPER, BODY KIT, RR END PNL, TAILGATE, RHR FENDER & RR FLR PNL. REPAIR ROOF TOP, RR CHASSIS & LHR FENDER                       | New      | 5,400.00         | 2,250.00        |
| 2                               | RESPRAY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, TAILGATE, TAILGATE SPOILER, RR FLR PNL, LHR FENDER, RHR FENDER, ROOF TOP & RR CHASSIS | New      | 3,500.00         | 1,575.00        |
| 3                               | REMOVE & REFIT TAILGATE COMPONENT                                                                                                        | New      | 120.00           | 120.00          |
| 4                               | REMOVE & REFIT FUEL TANK ASSY                                                                                                            | New      | 200.00           | 0.00            |
| 5                               | REMOVE & REFIT RR FLR BOARD, TRIM, RR FLR CARPET & RR SEAT TO GIVE WAY FOR REPAIR                                                        | New      | 200.00           | 120.00          |
| 6                               | CHECK WIRING ELECTRICAL SYSTEM                                                                                                           | New      | 30.00            | 30.00           |
| 7                               | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM                                                                               | New      | 120.00           | 120.00          |
| 8                               | CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH                                                                                                | New      | 1,000.00         | 0.00            |
| 9                               | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT                                                                                              | New      | 120.00           | 0.00            |
| 10                              | RENEW RR WINDSCREEN GLASS                                                                                                                | New      | 240.00           | 240.00          |
| 11                              | SUPPLY RR WINDSCREEN SEALANT                                                                                                             | New      | 80.00            | 80.00           |
| 12                              | REMOVE & REINSTALL LHR FENDER QTR GLASS                                                                                                  | New      | 120.00           | 0.00            |
| 13                              | REMOVE & REINSTALL RHR FENDER QTR GLASS                                                                                                  | New      | 120.00           | 120.00          |
| 14                              | INSTALL LHR & RHR FENDER QTR GLASS SOLAR FILM                                                                                            | New      | 240.00           | 0.00            |
| 15                              | SUPPLY QTR GLASS SEALANT                                                                                                                 | New      | 80.00            | 80.00           |
| 16                              | SUPPLY RR NUMBER PLATE WITH CASING                                                                                                       | New      | 80.00            | 50.00           |
| 17                              | REMOVE & REFIT REVERSE SENSOR                                                                                                            | New      | 80.00            | 80.00           |
| 18                              | APPLY ANTI CORROSION ON AFFECTED AREAS                                                                                                   | New      | 80.00            | 40.00           |
| 19                              | SUPPLY BODY PNL SEALANT                                                                                                                  | New      | 80.00            | 80.00           |
| 20                              | SUPPLY C&C BADGE                                                                                                                         | New      | 40.00            | 40.00           |
| 21                              | REMOVE & REFIT HEADLINING TO FACILITATE REPAIR                                                                                           | New      | 200.00           | 120.00          |
| 22                              | REPLACE REAR END PANEL<br>(Supplementary)                                                                                                | New      | 450.00           | 450.00          |
| 23                              | REPAIR REAR FLOOR PANEL<br>(Supplementary)                                                                                               | New      | 225.00           | 225.00          |
| 24                              | REPLACE RH REAR TAILLAMP PANEL<br>(Supplementary)                                                                                        | New      | 225.00           | 225.00          |
| 25                              | RESPRAY ON REAR FLOOR PANEL<br>(Supplementary)                                                                                           | New      | 350.00           | 350.00          |
| 26                              | REMOVE & REPLACE REAR EXHAUST MUFFLER & CNTRE EXHAUST PIPE<br>(Supplementary)                                                            | New      | 400.00           | 400.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                          |          | <b>13,780.00</b> | <b>6,795.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >