

ASS. REC. BY:

Steve

REF:

CS/11621098553/EVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

N/S - 11/8/21

Veh No:

SLP1900U

Yr Regn:

24/11/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Daiter

C.C.

1998

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp. Reading

Rt: 7062

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

GF7W0700817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brakes: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyo

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

4

mm

L/Bal:

4

mm

D.O.A.

14/8/21

D.O.A.

16/8/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Time/Time, File, Pass to?



: Prel. Report



: Final Report

Time/Time, File Return to?

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Transportation:

Fees:

Others:

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (%)



: VV&I (1%)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/SELOTARIO EUAN IZMAL BIN ILYAS</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLP1900U / 24/11/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0700817</td></tr> <tr> <td>Engine No</td><td>4J11CQ8571</td></tr> <tr> <td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 STYLE (999)</td></tr> <tr> <td>Colour/Trim</td><td>DO1 COSMIC BLUE MET/ BK BLACK</td></tr> </table>	Cust No/Name	/SELOTARIO EUAN IZMAL BIN ILYAS	Reg No/Reg Date	SLP1900U / 24/11/202	Date In/Mileage	/ 0	Chassis No	GF7W0700817	Engine No	4J11CQ8571	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK
Cust No/Name	/SELOTARIO EUAN IZMAL BIN ILYAS														
Reg No/Reg Date	SLP1900U / 24/11/202														
Date In/Mileage	/ 0														
Chassis No	GF7W0700817														
Engine No	4J11CQ8571														
Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)														
Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina	14184			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								5400.00
RENEW RR BUMPER , BODY KIT , RR END PNL , TAILGATE , RHR FENDER & RR FLR PNL					5 X	450		2250
REPAIR ROOF TOP , RR CHASSIS & LHR FENDER								
E PNT98000								3500.00
RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , TAILGATE , TAILGATE SPOILER , RR FLR PNL , LHR FENDER , RHR FENDER , ROOF TOP & RR CHASSIS					4-5 X	350		1575
E PNT88000								120.00
REMOVE & REFIT TAILGATE COMPONENT								
A 13900099								200.00
REMOVE & REFIT FUEL TANK ASSY								
E PNT88000								200.00
REMOVE & REFIT RR FLR BOARD , TRIM , RR FLR CARPET & RR SEAT TO GIVE WAY FOR REPAIR								
E PNT88000								200.00
REMOVE & REFIT HEADLINING TO FACILITATE REPAIR								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								1000.00
CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
E PNT88000								240.00
RENEW RR WINDSCREEN GLASS								
M SUNDRY								80.00
SUPPLY RR WINDSCREEN SEALANT								
E PNT88000								120.00
REMOVE & REINSTALL LHR FENDER QTR GLASS								
E PNT88000								120.00
REMOVE & REINSTALL RHR FENDER QTR GLASS								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /SELOTARIO EUAN IZMAL BIN ILYAS Reg No/Reg Date SLP1900U / 24/11/202 Date In/Mileage / 0 Chassis No GF7W0700817 Engine No 4J11CQ8571 Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina	14184		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							120 240.00
INSTALL LHR & RHR FENDER QTR GLASS SOLAR FILM							80.00
M SUNDRY							780.00
SUPPLY QTR GLASS SEALANT							80.00
M SUNDRY							50 80.00
SUPPLY IN-CAR CAMERA (windscreen glass camera) - missing							80.00
M SUNDRY							80.00
SUPPLY RR NUMBER PLATE WITH CASING							220.00
E PNT88000							80.00
REMOVE & REFIT REVERSE SENSOR							40 80.00
M SUNDRY							80.00
SUPPLY REVERSE SENSOR							40 80.00
M SUNDRY							80.00
APPLY ANTI CORROSION ON AFFECTED AREAS							40 80.00
M SUNDRY							40.00
SUPPLY BODY PNL SEALANT							30.00
M SUNDRY							
SUPPLY C&C BADGE							
M SUNDRY							
Sundries							
M FACE,RR BUMPER					1.00	1018.00 23.00	783.86
M EXTENSION,RR BUMPER					1.00	360.00 23.00	277.20
M BRKT,R/BMPR FACE SIDE,LH					1.00	12.00 23.00	9.24
M BRKT,R/BMPR FACE SIDE,RH					1.00	12.00 23.00	9.24
M REINFORCEMENT,RR BUMPER,LH					1.00	79.00 23.00	60.83
M REINFORCEMENT,RR BUMPER,RH					1.00	79.00 23.00	60.83
M CLIP,ENG ROOM COVER					8.00	2.00 23.00	12.32
M PANEL ASSY,TAILGATE					1.00	989.00 23.00	761.53
M GARNISH,TAILGATE					1.00	496.00 23.00	381.92
M W/STRIP,TAILGATE OPENING					1.00	213.00 23.00	164.01
R HINGE,TAILGATE					2.00	46.00 23.00	70.84
M GAS SPRING,TAILGATE,LH					1.00	194.00 23.00	149.38
M GAS SPRING,TAILGATE,RH					1.00	194.00 23.00	149.38

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /SELOTARIO EUAN IZMAL BIN ILYAS Reg No/Reg Date SLP1900U / 24/11/202 Date In/Mileage / 0 Chassis No GF7W0700817 Engine No 4J11CQ8571 Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina	14184			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SENSOR, TAILGATE LOCK, LH				1.00	426.00	23.00	328.02
M	SENSOR, TAILGATE LOCK, RH				1.00	426.00	23.00	328.02
M	MOTOR, POWER TAILGATE				1.00	1986.00	23.00	1529.22
M	LATCH, TAILGATE				1.00	477.00	23.00	367.29
M	STRIKER, TAILGATE LATCH				1.00	19.00	23.00	14.63
M	GLASS, TAILGATE WINDOW				1.00	657.00	23.00	505.89
M	DAM, TAILGATE SIDE				2.00	27.00	23.00	41.58
M	FASTENER, WINDSHIELD				4.00	6.00	23.00	18.48
M	DAM, TAILGATE, UPR				1.00	13.00	23.00	10.01
M	STOPPER, WINDSHIELD GLASS				2.00	3.00	23.00	4.62
M	DAM, TAILGATE, LWR				1.00	41.00	23.00	31.57
M	MARK, OUTLANDER				1.00	95.00	23.00	73.15
M	PANEL, RR END				1.00	326.00	23.00	251.02
M	PANEL, RR END, INR LH				1.00	0.00	23.00	
M	PANEL, RR END, INR RH				1.00	146.00	23.00	112.42
M	TRIM, RR END				1.00	113.00	23.00	87.01
M	BOX, CARGO FLOOR				1.00	204.00	23.00	157.08
M	LID, CARGO FLOOR BOX				1.00	295.00	23.00	227.15
M	ANT, KEYLESS OPERATION, RR				1.00	96.00	23.00	73.92
M	BUZZER, KEYLESS OPERATION, RR				1.00	88.00	23.00	67.76
M	DUCT, RR VENTILATOR				1.00	44.00	23.00	33.88
M	PANEL, QTR, OTR RH				1.00	1131.00	23.00	870.87
M	EXTN, QTR PANEL, RR LWR RH				1.00	78.00	23.00	60.06
M	EXTENSION, QTR PANEL, OTR RH				1.00	276.00	23.00	212.52
M	GLASS, QTR WINDOW, RH				1.00	679.00	23.00	522.83
M	FLOOR, RR				1.00	751.00	23.00	578.27
M	LAMP ASSY, COMB, RR LH				1.00	603.00	23.00	464.31
M	LAMP ASSY, COMB, RR RH				1.00	603.00	23.00	464.31
M	LAMP ASSY, TAIL, LH				1.00	506.00	23.00	389.62
M	LAMP ASSY, TAIL, RH				1.00	506.00	23.00	389.62
M	REFLECTOR, TAIL LAMP, LH				1.00	100.00	23.00	77.00
M	REFLECTOR, TAIL LAMP, RH				1.00	100.00	23.00	77.00
M	LAMP ASSY, LICENSE PLATE				2.00	34.00	23.00	52.36

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ATG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /SELOTARIO EUAN IZMAL BIN ILYAS Reg No/Reg Date SLP1900U / 24/11/202 Date In/Mileage / 0 Chassis No GF7W0700817 Engine No 4J11CQ8571 Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina	14184		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MOULDING,RR WHEEL ARCH,LH			1.00	168.00	23.00	129.36
M	MOULDING,RR WHEEL ARCH,RH		APC	1.00	168.00	23.00	129.36
M	MOULDING,RR BUMPER,LH		APC	1.00	88.00	23.00	67.76
M	MOULDING,RR BUMPER,RH		APC	1.00	88.00	23.00	67.76
M	TRIM,TAILGATE		GR	1.00	329.00	23.00	253.33
M	BODY KIT, OUTLANDER		GR ?	1.00	1554.00	20.00	1243.20
M	REAR SPOILER,COSMIC BLUE			1.00	511.00	20.00	408.80
M	DECAL,MIVEC		APC	1.00	36.00	23.00	27.72

Estimate

SURVEYOR NAME: Steve (LKK) 16/8/21, 4.30 PMSURVEYOR SIGNATURE: OD- NY ALDATE: EXCESS - ?REMARKS: P/P, My Bel Sm12 dys

LKK Auto Consultants hence notify

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on **Nett** **26,799.36**
1875.96
Total Payable 28,675.32

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.