

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008556/T1PA3Q2
Date: 01/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800106948
Claimant Vehicle No :	SHC6405R	Insured Vehicle No :	GBE1882P
Date of Loss:	14/08/2021	Nature of Claim:	TP
		Claim No:	1975815259SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6405R	Engine No:	D4FDEH313575
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5588606
Reg. Date:	19/03/2015 (Man. Year: 2014)	Odometer:	723355 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,062.40	1,041.90	3,020.50	74.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	810.00	1,690.00	67.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,562.40	1,851.90	4,710.50	71.78
Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	6,562.40	1,450.00	5,112.40	77.90
+ GST 7.00/7.00% (S\$)	459.37	101.50	357.87	77.90
Nett Amount (S\$)	7,021.77	1,551.50	5,470.27	77.90
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$50.99/day) (S\$)		203.96		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,957.46		
Global Sum Settlement (S\$)		1,950.00		

INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 16/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Not Necessary	1,028.00 FL	*- FL
2	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
3	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
4	1		*FRONT BUMPER N/S SIDE RETAINER	Necessary	16.00 FL	*16.00 FL
5	1		*FRONT BUMPER N/S UPPER BRACKET	Not Necessary	16.00 FL	*- FL
6	1		*FRONT BUMPER N/S SUPPORT BRACKET	Not Necessary	16.00 FL	*- FL
7	1		*FRONT N/S FENDER	Bent	384.00 FL	*384.00 FL
8	1		*FRONT N/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
9	1		*FRONT N/S LOWER ARM	Not Necessary	439.00 FL	*- FL
10	1		*FRONT N/S SHOCK ABSORBER	Not Necessary	330.00 FL	*- FL
11	1		*FRONT N/S BALL JOINT	Not Necessary	59.00 FL	*- FL
12	1		*FRONT N/S TIE ROD END	Not Necessary	61.00 FL	*- FL
13	1		*FRONT N/S KNUCKLE BEARING	Not Necessary	157.00 FL	*- FL
14	1		*FRONT N/S STABILIZER LINK	Not Necessary	86.00 FL	*- FL
15	1		*FRONT N/S KNUCKLE ARM	Not Necessary	547.00 FL	*- FL
16	1		*FRONT N/S RIM	Not Necessary	246.00 FL	*- FL
17	1		*FRONT N/S WHEEL COVER	Deformed	116.00 FL	*116.00 FL
18	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
20	1		*FRONT N/S FENDER STICKER	Necessary	60.00 FS	*30.00 FS
21	1		*SET N/S DOOR STICKERS	Not Necessary	100.00 FS	*- FS
22	1		*SUNDRY FEE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,482.00	1,151.00
- List Item Discount on L Items 10.00/10.00% (S\$)	419.60	109.10
Total Parts (S\$)	4,062.40	1,041.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	80.00
2	TO CHECK HEADLAMP WIRING	New	40.00	0.00
3	TO DISMANTLE AND REPLACE FRONT N/S UNDERCARRIAGE	New	250.00	0.00
4	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
5	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE FRONT N/S DOOR ,FRONT N/S WHEEL HOUSE ETC	New	900.00	300.00
6	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,FRONT N/S DOOR ,FRONT N/S WHEEL HOUSE ,N/S MIRROR COVER	New	900.00	400.00
7	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	30.00
Gross Labour Cost (S\$)			2,500.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >