9/7/21, 12:33 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI21008561/KTCN2 Our File No:

07/09/2021 Date:

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer: Pte. Ltd.

Policy No:

DMPCSNW00113272100

Claimant Vehicle

Insured Vehicle

No:

SMA9032P

No:

SJA1395E

Date of Loss:

Nature of Claim:

Claim

Chassis No:

Odometer:

44635 km

WAUZZZ8V2J1063918

Reg. Date:

13/08/2021

TP

No:

SNM21D204513/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMA9032P Reg No:

Make & Model: AUDI A3, 999cc SEDAN TFSI (A)

Engine No: CHZ929559

Colour: Metallic Dark Blue

999 cc

22/06/2018 (Man. Year: 2018)

Engine Capacity:

N/A Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,120.75	1,904.92	1,215.83	38.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	480.00	870.00	64.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,470.75	2,384.92	2,085.83	46.66
+ GST 7.00/7.00% (S\$)	312.95	166.94	146.01	46.66
Nett Amount (S\$)	4,783.70	2,551.86	2.231.84	46.66

INSPECTION

Date of Assignment: 16/08/2021

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & Date Inspected: 19/08/2021 Inspected At: 17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: **KENNETH KONG** Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

9/7/21, 12:33 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2021)

Parts: 144 AUDI A3 999cc SEDAN TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMA9032P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,050.00 FL	*1,050.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
3	2		*REAR BUMPER BRACKET	Serviceable	110.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	80.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	380.00 FL	*- FL
6	1		*REAR BUMPER REVERSE SENSORS (2 Pcs)	Shorted (1 Pc only)	310.00 FL	*155.00 FL
7	1		*REAR BUMPER LOWER LIP	Cracked	520.00 FL	*468.65 FL
8	1		*REAR BUMPER INNER CORE	Cracked	280.00 FL	*191.00 FL
9	1		*BOOT EMBLEM	Not Necessary	85.00 FL	*- FL
10	1		*BOOT BADGE A3	Not Necessary	100.00 FL	*- FL
11	1		*BOOT BADGE TFSI	Not Necessary	100.00 FL	*- FL
12	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	171.00 FS	*48.00 FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	3,276.00	2,002.65
			- List Item Discount o	on L Items 5.00/5.00% (S\$)	155.25	97.73
				Total Parts (S\$)	3,120.75	1,904.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CONDUCT ELECTRICAL CHECK, REPLACE REVERSE SENSORS & REPROGRAM SYSTEM	New	150.00	60.00
2	LABOUR CHARGE-PANEL BEATING,REPAIRING OF BOOT,END PANEL AND PART REPLACEMENT	New	600.00	200.00
3	TO RESPRAY AFFECTED AREAS	New	600.00	220.00
	Gross Labour Cost (S\$)		1,350.00	480.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >