



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 6767B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR (CONSISTENT)	BENT	921.00	921.00
1	FRONT DOOR STICKER (CONSISTENT)	NECESSARY	45.00	45.00
1	REAR DOOR (CONSISTENT)	BENT	996.00	996.00
1	REAR DOOR STICKER (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,133.00	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	830.00	-
1	REAR AXLE (CONSISTENT)	BENT	1,096.00	1,096.00
	LESS 10% DISCOUNT		-	-311.30
			5,076.00	2,801.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SPROTS RIM (RAY S) (SN) (CONSISTENT)	DENTED	450.00	450.00
			450.00	450.00
	<b><u>LABOUR</u></b>			
	WHEEL ALIGNMENT.		50.00	50.00
	TO REMOVE REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO RESPRAY ALL AFFECTED PARTS.		1,000.00	800.00
	TO REMOVE ALL DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER AND REAR BUMPER.		900.00	600.00
	REMOVE UNDERCARRIAGE.		150.00	150.00
			2,250.00	1,600.00
	<b>GRAND TOTAL</b>		<b>7,776.00</b>	<b>4,851.70</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,850.00</b>

Report Ref No. CS/ASM21008564/Kqce2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.