9/21/21, 9:07 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008565/KTF3N2

21/09/2021 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001621775 **Claimant Vehicle**

SKT9903A Insured Vehicle No: **SLK5576Y** No:

Date of Loss: 12/08/2021 Nature of Claim: ΤP Claim No: 261172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9903A**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) 2ZR0B89875 Engine No: Reg. Date: 20/12/2018 (Man. Year: 2018) Chassis No: ZWR800329404 Colour: Odometer: 47930 km Metallic Grey

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Goodyear 6 mm Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,115.00	1,236.00	879.00	41.56
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,390.00	1,110.00	1,280.00	53.56
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,505.00	2,346.00	2,159.00	47.92
	Approved Total (Overridden) (S\$)		1,850.00		
	(S\$)	4,505.00	1,850.00	2,655.00	58.93
	+ GST 7.00/7.00% (S\$)	315.35	129.50	185.85	58.93
	Nett Amount (S\$)	4,820.35	1,979.50	2,840.85	58.93

INSPECTION

Date of Assignment: 17/08/2021

MBM Wheelpower Pte Ltd (Sin Ming) Date Inspected: 31/08/2021 Inspected At:

176 Sin Ming Drive #01-15, Sin Ming AutoCare

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

	•			
டு	\sim \pm	0r	\sim	\sim
~ .				
,		\sim 1	C I I	ce

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2021)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT9903A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	1,490.00 FL	*1,458.00 FL
2	1		*REAR RH DOOR WEATHERSTRIP	Serviceable	180.00 FL	*- FL
3	1		*REAR RH DOOR HINGE UPP	Repair	95.00 FL	*- FL
4	1		*REAR RH DOOR HINGE LOWER	Repair	95.00 FL	*- FL
5	1		*REAR RH DOOR CHROME	Necessary	190.00 FL	*190.00 FL
6	1		*REAR RH FENDER	Repair	450.00 FL	*- FL
7	1		*RH SIDE SKIRT GARNISH	Repair	320.00 FL	*- FL
+=+ra	inchise	part. L=ListIter	nuisc.	Sub Total (S\$)	2,820.00	1,648.00
			- List Item Discount on	L Items 25.00/25.00% (S\$)	705.00	412.00
				Total Parts (S\$)	2,115.00	1,236.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	900.00	400.00
2	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	150.00	60.00
3	TO APPLY ANTI RUST COATING	New	150.00	30.00
4	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	0.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
6	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	600.00
	Gross Labour Cost (S\$)		2,390.00	1,110.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >