

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008571/BRS3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456060
Claimant Vehicle No :	SMD4724T	Insured Vehicle No :	SFZ3579U
Date of Loss:	13/08/2021	Nature of Claim:	TP
		Claim No:	9543109191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD4724T	Engine No:	CAXE90250
Make & Model:	VOLVO V40, 1.5 T2 (A)	Chassis No:	WVWZZZ3CZEE176677
Reg. Date:	14/07/2014 (Man. Year: 2014)	Odometer:	100120 km
Colour:	Brown		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,877.71	12,869.73	18,007.98	58.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,600.00	3,150.00	5,450.00	63.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,477.71	16,019.73	23,457.98	59.42
Approved Total (Overridden) (\$\$)		9,383.00		
(\$\$)	39,477.71	9,383.00	30,094.71	76.23
+ GST 7.00/7.00% (\$\$)	2,763.44	656.81	2,106.63	76.23
Nett Amount (\$\$)	42,241.15	10,039.81	32,201.34	76.23
+ Car Rental (12.0 x \$S\$100.00/day + 7.00% GST) (\$\$)		1,284.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		11,331.26		

INSPECTION

Date of Assignment:	16/08/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	16/08/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	10.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,682.60 FL	*1,450.00 FL
2	1		*BOOTLID LOGO	Necessary	118.30 FL	*89.20 FL
3	1		*BOOTLID EMBLEM PASSAT	Necessary	84.50 FL	*62.00 FL
4	1		*BOOTLID INNER LOCK	Jammed	365.70 FL	*162.50 FL
5	1		*BOOTLID INNER LOCK STRICKER	Not Damaged	184.60 FL	*- FL
6	2		*BOOTLID INNER TRIM BOARD	Not Damaged	652.40 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Damaged	269.70 FL	*- FL
8	2		*BOOTLID LAMP	Not Damaged	970.60 FL	*- FL
9	1		*BOOTLID OUTER CHROME MOULDING	Broken	148.00 FL	*148.00 FL
10	1		*REAR BUMPER	Broken	1,876.30 FL	*1,147.92 FL
11	1		*REAR BUMPER LOWER	Broken	458.00 FL	*323.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	391.20 FL	*187.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	485.20 FL	*485.20 FL
14	2		*REAR BUMPER SIDE CHROME MOULDING	Broken	772.80 FL	*348.50 FL
15	2		*REAR BUMPER BRACKET	No such part	220.40 FL	*- FL
16	1		*REAR BUMPER CENTRE BRACKET	Bent	280.00 FL	*69.96 FL
17	2		*REAR BUMPER NUMBER PLATE LAMP	Not Damaged	136.00 FL	*- FL
18	1		*REAR END PANEL	Dented	1,168.30 FL	*962.50 FL
19	1		*REAR END PANEL TOP GARNISH	Not Damaged	248.60 FL	*- FL
20	2		*TAILLAMP	Broken	1,591.60 FL	*1,022.60 FL
21	2		*TAILLAMP LOWER BRACKET	Not Damaged	252.80 FL	*- FL
22	1		*BONNET	Bent	1,655.90 FL	*1,380.97 FL
23	1		*BONNET LOCK ASSY	Not Damaged	234.60 FL	*- FL
24	1		*BONNET INSULATOR PAD	Not Damaged	426.00 FL	*- FL
25	1		*FRONT BUMPER	Broken	1,557.30 FL	*1,103.66 FL
26	2		*FRONT BUMPER SIDE RETAINER	Necessary	368.00 FL	*59.40 FL
27	1		*FRONT BUMPER REINFORCEMENT	Dented	486.00 FL	*260.00 FL
28	1		*FRONT BUMPER CENTRE GRILLE	Broken	198.60 FL	*146.00 FL
29	3		*FRONT BUMPER OUTER CHROME MOULDING	Necessary	540.00 FL	*540.00 FL
30	2		*FRONT BUMPER FOG LAMP GARNISH	Broken	252.40 FL	*252.40 FL
31	1		*FRONT BUMPER FOG LAMP GARNISH CHROME MOULDING	Not Damaged	316.00 FL	*- FL
32	1		*FRONT BUMPER TOW CAP	Not Damaged	83.20 FL	*- FL
33	1		*FRONT GRILLE	Broken	899.90 FL	*600.87 FL
34	1		*FRONT GRILLE LOGO	Necessary	89.00 FL	*89.00 FL
35	1		*FRONT GRILLE BASE	No such part	413.60 FL	*- FL
36	1		*FRONT LICENSE PLATE	Broken	98.00 FL	*50.00 FL
37	1		*FRONT FENDER RH	Repair	1,148.30 FL	*- FL
38	1		*FRONT FENDER INNER COWLING	Not Damaged	241.00 FL	*- FL
39	2		*HEADLAMP ASSY	Broken	3,664.40 FL	*2,003.46 FL
40	2		*HEADLAMP BRACKET	No such part	290.00 FL	*- FL
41	1		*FRONT SUPPORT PANEL	Broken	898.00 FL	*600.00 FL
42	1		*FRONT SUPPORT TOP PANEL GARNISH	Not Damaged	185.00 FL	*- FL
43	1		*RADIATOR	Not Damaged	987.90 FL	*- FL
44	1		*AIRCON CONDENSER	Not Damaged	1,158.00 FL	*- FL
45	1		*AIRCON SUCTION HOSE	Not Damaged	398.00 FL	*- FL
46	1		*AIRCON DISCHARGE HOSE	Not Damaged	352.00 FL	*- FL
47	1		*AIR DUCT	Not Damaged	86.90 FL	*- FL
48	1		*INTERCOOLER	Not Damaged	1,756.30 FL	*- FL
49	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
50	1		*BOOTLID SEALANT	Necessary	100.00 FS	*40.00 FS
51	2		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
52	2		*BOOTLID LAMP SEAL	Not Necessary	120.00 FS	*- FS
53	2		*BOOTLID LAMP CLIPS	No such part	100.00 FS	*- FS
54	1		*BOOTLID OUTER CHROME MOULDING CLIPS	Necessary	50.00 FS	*20.00 FS
55	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
57	2		*REAR BUMPER SIDE CHROME MOULDING CLIPS	Necessary	100.00 FS	*40.00 FS
58	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
59	1		*REAR END PANEL TOP GARNISH CLIPS	Not Damaged	50.00 FS	*- FS
60	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
61	2		*TAILLAMP SEAL	Necessary	120.00 FS	*60.00 FS
62	1		*REAR REVERSE CAMERA	Not Damaged	480.00 FS	*- FS
63	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
64	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS
65	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
66	1		*BONNET INSULATOR PAD CLIPS	Not Necessary	50.00 FS	*- FS
67	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
68	1		*FRONT BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS
69	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
70	1		*FRONT SUPPORT PANEL GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*AIRCON FLUID	Necessary	120.00 FS	*30.00 FS
72	1		*RADIATOR COOLANT	Necessary	120.00 FS	*30.00 FS
73	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	33,991.90	14,224.14
- List Item Discount on L Items 10.00/10.00% (\$)	3,114.19	1,354.41
Total Parts (\$)	30,877.71	12,869.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENTS	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	REAR CHECK WIRING	New	100.00	20.00
4	REAR UPHOLSTERY	New	300.00	0.00
5	REAR PANEL BEATING	New	1,600.00	600.00
6	REAR RUST PROOFING	New	200.00	0.00
7	REAR SPRAY PAINTING	New	1,600.00	600.00
8	R&R RADIATOR	New	150.00	50.00
9	R&R CONDENSER	New	150.00	50.00
10	R&R INTERCOOLER	New	150.00	50.00
11	FRONT CHECK WIRING	New	100.00	20.00
12	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
13	REAR UPHOLSTERY	New	300.00	0.00
14	FRONT PANEL BEATING	New	1,600.00	800.00
15	FRONT RUST PROOFING	New	200.00	0.00
16	FRONT SPRAY PAINTING	New	1,600.00	700.00
Gross Labour Cost (\$\$)			8,600.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >