

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 5002G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DENTED	800.00	648.00
1	REAR BUMPER LOWER SKIRT GARNISH (CONSISTENT)	CUT	650.00	450.00
2	REAR BUMPER REFLECTOR LAMP LH / RH (CONSISTENT)	NOT NECESSARY	320.00	-
2	REAR BUMPER SIDE RETAINER LH / RH (CONSISTENT)	BROKEN	180.00	140.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	550.00	382.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	38.00	30.00
1	REAR TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,150.00	-
1	REAR TAILGATE SUBARU EMBLEM (CONSISTENT)	NECESSARY	150.00	90.00
1	REAR TAILGATE IMPREZA EMBLEM (CONSISTENT)	NECESSARY	85.00	85.00
1	REAR TAILGATE CENTRE GARNISH (CONSISTENT)	CUT	310.00	270.00
1	SET REAR TAILGATE CENTRE GARNISH FASTERNERS (CONSISTENT)	NECESSARY	38.00	10.00
1	REAR TAILGATE W/SCREEN MOULDING (CONSISTENT)	NOT NECESSARY	285.00	-
2	REAR TAILGATE LAMP LH / RH (CONSISTENT)	N/S CUT	760.00	380.00
1	REAR TAILGATE INNER LOCK (CONSISTENT)	NOT NECESSARY	298.00	-
1	REAR TAILGATE INNER WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	285.00	-
1	REAR TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	330.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	38.00	-
2	REAR TAILLAMP LH / RH (CONSISTENT)	NOT NECESSARY	860.00	-
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	650.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	320.00	-
2	REAR FENDER INNER TRIM BOARD LH / RH (CONSISTENT)	NOT NECESSARY	1,280.00	-
2	SET REAR FENDER INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	75.00	-
1	REAR SPARE TYRE PANEL (CONSISTENT)	NOT NECESSARY	880.00	-
1	REAR SPARE TYRE TOP COVER (CONSISTENT)	NOT NECESSARY	450.00	-
	LESS 20% DISCOUNT		-2,156.40	-497.00
			8,625.60	1,988.00

Report Ref No. CS/ASM21008572/Etce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	200.00	200.00
1	REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR SPARE TYRE PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SUBARU ORIGINAL IN-BUILD LCD SCREEN (SN) (BROKEN)	NOT CONSISTENT WITH THE IMPACT	3,200.00	-
			3,890.00	200.00
	<u>LABOUR</u>			
	SPRAYING OF AFFECTED AREA.		600.00	400.00
	CARRY OUT BODY CAVITY PRESERVATION.		100.00	30.00
	TO REMOVE AND REPLACE DAMAGE PARTS INCLUDING STRAIGHTENING & REPOSITIONING REPLACEMENT PARTS & PANEL BEAT. INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		800.00	300.00
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	CHECK WIRING.		60.00	30.00
	REMOVE / REFIX BOOT COMPARTMENT FITTING.	NOT NECESSARY	80.00	-
	REMOVE & REFIX REVERSE CAMERA.	NOT NECESSARY	80.00	-
	REMOVE & REFIX REVERSE SENSOR.		80.00	30.00
	REMOVE & REFIX TAILGATE COMPONENTS.	NOT NECESSARY	80.00	-
	REMOVE & REFIX FRONT IN-BUILD LCD SCREEN.	NOT NECESSARY	150.00	-
			2,180.00	790.00
	GRAND TOTAL		14,695.60	2,978.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/ASM21008572/Etce2



Automotive Assessor

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser