

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008576/KVCN2**Date:** 01/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00077202100

Claimant Vehicle No : SLL7768S **Insured Vehicle No :** XD6389J

Date of Loss: 14/08/2021 Nature of Claim: TP Claim No: SNM21D204516/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7768S**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4404948

Reg. Date: 09/03/2017 (Man. Year: 2016) Chassis No: RU11204943

Colour: Metallic Blue Odometer: 110252 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Double Star 7 mm Rear Left Side: Double Star 9 mm

Front Right Side: Double Star 7 mm Rear Right Side: Double Star 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,336.00	2,088.80	2,247.20	51.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,410.00	530.00	27.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,276.00	3,498.80	2,777.20	44.25
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	6,276.00	3,450.00	2,826.00	45.03
+ GST 7.00/7.00% (S\$)	439.32	241.50	197.82	45.03
Nett Amount (S\$)	6,715.32	3,691.50	3,023.82	45.03

INSPECTION

Date of Assignment: 16/08/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 16/08/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL7768S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Bent	190.00 F	*190.00 FL
2	1		*1 PC FRT BUMPER REINFORCEMENT	Bent	205.00 F	*205.00 FL
3	1		*1 PC FRT BUMPER RH SIDE RETAINER	Missing	10.00 F	*10.00 FL
4	1		*1 PC FRT BUMPER LOWER SKIRT	Buckled	145.00 F	*145.00 FL
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE	Distorted	60.00 F	*60.00 FL
6	1		*1 PC FRT BUMPER RH FOG LAMP	Serviceable	135.00 F	*- FL
7	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH	Distorted	18.00 F	*18.00 FL
8	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 FL
9	1		*1 PC FRT GRILLE HOUSING	Cracked	200.00 F	*200.00 FL
10	1		*1 PC FRT GRILLE TOP COVER	Serviceable	160.00 F	*- FL
11	1		*4 PCS FRT GRILLE CLIPS @2/PC	Necessary	8.00 F	*8.00 FL
12	1		*1 PC RH HEADLAMP	Mtg Cracked	880.00 F	*880.00 FL
13	1		*1 PC RH HEADLAMP LOWER RETAINER	Cracked	25.00 F	*25.00 FL
14	1		*1 PC RH HEADLAMP SDIE BRACKET	Repair	15.00 F	*- FL
15	1		*1 PC LH HEADLAMP	Serviceable	880.00 F	*- FL
16	1		*1 PC FRT RH FENDER	Buckled	190.00 F	*190.00 FL
17	1		*1 PC FRT RH FENDER WHEEL ARP GARNISH	Buckled	60.00 F	*60.00 FL
18	1		*1 PC FRT RH FENDER INNER PANEL	Repair	180.00 F	*- FL
19	1		*1 PC FRT SUPPORT PANEL	Repair	320.00 F	*- FL
20	1		*1 PC BONNET	Bent	495.00 F	*495.00 FL
21	1		*1 PC BONNET RH INNER RUBBER	Cut	20.00 F	*20.00 FL
22	1		*1 PC BONNET RH HINGE	Repair	35.00 F	*- FL
23	1		*1 PC FRT WIPER TANK	Dented	55.00 F	*55.00 FL
Supplementary #1						
24	1		*1 PC FRT WIPER TANK MOTOR	Cracked	38.00 F	*38.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,336.00	2,611.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	522.20
Total Parts (\$\$)	4,336.00	2,088.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FOG LAMPS & GARNISHS,HEADLAMPS,BONNET & ATTACHMENT,CUT,WELD & RENEW FRT SUPPORT PANEL,FRT RH FENDER INNER PANEL & REALIGN THE SAME	New	980.00	600.00
2	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00	0.00
3	PUTTY & RESPRAY ON FRT SUPPORT PANEL,BONNET,HINGES,FRT BUMPER,REINFORCEMENT,FR TFENDER & ALL AFFECTED AREAS	New	800.00	750.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,940.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >