

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21008577/AES3Q2
Date: 18/11/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SCE1277A	Insured Vehicle No :	SMM9479X
Date of Loss:	14/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCE1277A		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520274820
Reg. Date:	13/05/2015 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0308227
Colour:	Red	Odometer:	45160 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,923.04	4,331.68	1,591.36	26.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,210.00	720.00	37.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,853.04	5,541.68	2,311.36	29.43
Approved Total (Overridden) (S\$)		4,400.00		

(S\$)	7,853.04	4,400.00	3,453.04	43.97
+ GST 7.00/7.00% (S\$)	549.71	308.00	241.71	43.97
Nett Amount (S\$)	8,402.75	4,708.00	3,694.75	43.97
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,224.45		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 16/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCE1277A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	971.40 FL	*971.40 FL
2	10		*FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
3	1		*FRONT BUMPER N/S FOG LAMP	Cracked	265.20 FL	*265.20 FL
4	1		*FRONT BUMPER N/S FOG LAMP (GARNISH)	Cut	86.50 FL	*86.50 FL
5	1		*FRONT BUMPER N/S RETAINER	Necessary	64.00 FL	*64.00 FL
6	2		*FRONT N/S & N/S GRILLE COVER (LOWER)	Not Necessary	80.00 FL	*- FL
7	1		*FRONT N/S HEAD LAMP	Cut	1,277.80 FL	*1,277.80 FL
8	1		*FRONT N/S FENDER	Dented	385.70 FL	*385.70 FL
9	1		*FRONT N/S RIM	Cut	1,005.44 FS	*600.00 FS
10	1		*FRONT N/S LOWER ARM	Bent	554.30 FL	*484.00 FL
11	1		*FRONT N/S TIE ROD END	Not Necessary	249.40 FL	*- FL
12	1		*FRONT N/S STABILIZER LINKAGE	Not Necessary	168.00 FL	*- FL
13	1		*FRONT N/S SUSPENSION	Bent	460.80 FL	*381.00 FL
14	1		*FRONT N/S BEARING	Damaged	658.80 FL	*364.00 FL
15	1		*FRONT N/S KUNCKLE	Not Necessary	502.60 FL	*- FL
16	1		*FRONT N/S TYRE	Cut	150.00 FS	*120.00 FS
17	1		*FRONT N/S FENDER INNER TRIM	Deformed	210.00 FL	*210.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,109.94	5,229.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,186.90	897.92
Total Parts (\$\$)	5,923.04	4,331.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE STRAIGHTEN & WELDING	New	800.00	500.00
2	TO SPRAY PAINTING	New	600.00	400.00
3	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
4	TO REMOVE AND REPLACE FRONT N/S UNDER CARRIAGE	New	300.00	200.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO RE-SEAL ANTI-RUST	New	30.00	0.00
Gross Labour Cost (S\$)			1,930.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >